APR 2 9 1996

JUDITH D. ROEHM Ontonason County 3/343 JEM 10/19/95

9.00 Fee:

Page

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requ	irement of Act 74, Mich. P.A.	. 1970
Ontonagon (County)	Located in:	Corner Code #	
Public Land Survey	T <u>52N</u> R <u>39V</u> T R T R T R		
Property Controlling in Section	S T R S T R		
3. Miscellaneous	S T R		
Property in Section			Register of Deeds Stamp & File Number
4. Lot No, R	ecorded Plat		A B C D E F G H i J K L N
5. Private Claims			
			2 - 6 - 5 - 1 - 4 - 3 2 1
			3
			4 7 8 9 10 11 - 12 -
I, Joseph C. Domitrovich	, in a field survey on	October 5 , 19 95	
do hereby certify that under req	purements of P.A. 74, Michigan onformance with regulations an	P.A. of 1970, the corner points mention drules therefore as required in the cur	oned 6 18 17 16 15 14 13 rrent
manual of survey instructions	of the United States Depa	rtment of the Interior, Bureau of L	_and
Management or by a decree of	a Court of Law and/or that the	corner points mentioned in lines 3, 4	and 8 19 20 21 22 23 24
5 above were in conformance	with the rules of the Michigan	Board of Professional Surveyors or bented, re-monumented, recovered, fo	by a 9
as expressed below:	Distied, re-established, mondi-	isited, re-monumented, recovered, to	10 30 29 28 27 26 25 -
NOTE: Not more than 4 cor on this certificate.	rners, all in the same town a	nd range, may be recorded	11 32 33 34 35 36 36 36 36 36 36 36 36 36 36 36 36 36
A. Description of original	monument and accessories	s and/or subsequent restoration:	
South 1/4 Corner Section 3	33, T52N, R39W	-	

1845 - William A. Burt set 1/4 section post 14" Hemlock N 67° E 22

9" Sugar

N 64⁰ W

22 links 9 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

All evidence of original corner has been obliterated by extensive farming. An old East-West fenceline falls of the North side of a cleared field. A newer fenceline falls just to the south of it.

Corner position was re-established midway between standard section corners, and the older fence was used to establish the North-South position.

(Research on file with County Remonumentation Representative.)

C. I	Description of monument for corner and access	sories established to pe	erpetuate locating the p	position of the corner:	
Corne	ner is an aluminum pipe with 3" diameter stam	ped aluminum cap an	id fails on an old East	t-West fenceline at the	North side

of a field. Witnesses:

6" poplar

12" Red Pine

30" Soft Maple

North 1/4 Corner Section 4, T51N, R39W (Stamped Monument)

N 230 E N 80⁰ E

N 300 W

Sign Post

South

0.45

7.18

23.71

24.30

East

52.80"

NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

_ Date_

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

TOSEPH

DOMITROVICH