

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 16 T 53N R 37W	9
	S 16 T 53N R 37W	SMC N. of F6
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5						LAKE							
6		16		17		18		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on SMC 07/30/2012 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 16) East 1/16 corner, Section 16. Not previously monumented.

(SMC N. of F6) Special Meander Corner on N-S 1/4 line, North of F6. 2006 - Established by Todd G.  
Maki PS #49300 and recorded in LC7 - PG362. Set 5/8" capped rebar. Snow fence T-iron N50W 25.01',  
5" W.Cedar N04W 9.87', 13" W.Spruce N84E 19.85', 10" Red Maple S51W 7.55'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 16) Established the position for the corner midway and on a straight line between Center of  
Section 1378.70' west and Quarter corner 1378.70' east. The position for the corner cannot be  
satisfactorily monumented and so I established a Witness Corner on the E-W 1/4 line 189.50' west of  
the corner position.

(SMC N. of F6) Found a 5/8" dia. rebar in good condition, with cap #47949, at record bearing and  
distance from two remaining 2006 BTs and the snow fence T-iron. Accepted same as a careful and  
faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap,  
a Witness Corner 189.50' west of corner #9.  
Set measuring nail with MDNR tag in the side of:  
4" Cedar N70E 7.15' mrkd "WC BT"  
7" Cedar S74E 10.15' do  
3" Hemlock S02E 9.75' do  
8" Cedar N72W 15.2' do  
Set sq'd Cedar post adjacent.  
Bearings are magnetic.

(SMC) Found 5/8" capped rebar.  
Snow fence T-iron N50W 25.01'  
Fd. duplex nail in:  
6" W.Cedar N04W 9.87'  
10" R.Maple S51W 7.55'  
Set measuring nail and MDNR tag in the side of:  
6" B.Spruce S09E 18.0' mrkd "SMC BT"  
Set sq'd Cedar post adjacent. Bearings mag.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/29/2012

For the Michigan Department of Natural Resources, Forest Resources Division

