

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 21 T 53N R 37W S 21 T 53N R 37W S _____ T _____ R _____	10 12
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 10 08/08/2012  
12 08/27/2012 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10-Sec. 21) South 1/16 corner between Sections 20 and 21. Found no record of prior monumentation.

(12-Sec. 21) South 1/16 corner, Section 21. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10-Sec. 21) Established the position for the corner midway and on the Section line between Section  
corner 1334.64' south and Quarter corner 1334.64' north. From the position thus established, I found  
a 1.75" dia. iron pipe, not of record, set by persons unknown, 14.3' south, which I did not accept as  
marking the position for the corner. The found pipe was removed.

(12-Sec. 21) Established the position for the corner midway and on a straight line between Quarter  
corner 1333.11' south and Center of Section 21 1333.11' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
14" Hemlock N19E 17.85' mrkd "1/16S BT"  
6" Sugar N65E 15.05' do  
6" Sugar S15E 16.1' do  
15" Hemlock S62W 29.15' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

(12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
14" Spruce N25E 17.15' mrkd "1/16S BT"  
6" Y.Birch N78E 25.15' do  
7" Maple S43E 3.75' do  
9" Ash S83W 10.9' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/29/2012

For the Michigan Department of Natural Resources, Forest Resources Division

