LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #	5	
1. Public Land Survey	T 53N R 37W T 53N R 37W	C6 MC N. of C5		
2. Property Controlling in Section	S T R S T R			
3. Miscellaneous Property in Sec.	S T R R			
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Star	np & File Number
ı, Stephan J. Szyszkoski , i		22/2012 do hereby state	3 / / / / / /	- 9 2 1
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey				
instructions of the United States a Court of Law and /or that the o	Department of the Interior, Bureau of La corner points mentioned in lines 3, 4 and	and Management or by a decree of 5 above were in conformance with	6 18 17 16 7	15 14 13
re-established, monumented, recov	d of Land Surveyors or by a Decree ered, found as expressed below:		9 20 21	222324
	ners, all in the same town and range,	may be recorded	10 30 29 28	272625
on this certificate.		Ø	12 31 32 33	36 35 36

A. Description of original monument and accessories and/or subsequent restoration:

(C6) Quarter corner common to Sections 17-18. 1980 - K.L.Sackett RLS found and accepted an old cedar post. Set 1"IDx36" I.pipe with 4" alum. cap. 6" Cedar S22W 7.8', 4" Cedar N55W 12.3', 5" Cedar N86E 2003 - 1980 monument recovered in good condition and rewitnessed by the undersigned: 6" Cedar 9.81 N47E 15.5', 8" Cedar S67E 34.6', 5" Aspen S18E 11.9', 6" Aspen N81W 15.3'. Squared cedars 1.5' W'ly and 1.5' S'ly.

(MC N. of C5) Meander corner on the shore of Lake Superior between Sections 7 and 8. 1980 -K.L.Sackett RLS established a Witness Corner to the original Meander Corner, which is shown on the original plat as being 16.50 chains north of Section corner C5. Set 1"IDx36" I.pipe with 4" alum. 9" Spruce S05W 5.9', 6" Spruce S78E 24.9'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C6) Found the 1980 monument in good condition and at record bearing and distance from the 2003 witnesses, which were remeasured as described below.

(MC N. of C5) Found the 1980 monument in good condition and at record bearing and distance from the remaining 1980 accessory, described below. The monument was found to be 1060.59' north of Section corner C5, making its position 28.41' south of the original M.C. position. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C6) Found 1"ID I.pipe with 4" alum. MDNR cap. Fd. measuring nail with MDNR tag in the side of: 6" Cedar N46E 15.7' scribing plain scribing plain 8" Cedar S68E 34.6' do 9" Poplar S18E 11.75' overgrown blazes

8" Poplar N79W 15.01 Bearings are magnetic.

(MC) Found 1"ID I.pipe with 4" alum. MDNR cap for a WITNESS CORNER - the cap is stamped "Meander cor."

Set measuring nail with MDNR tag in the side of: 11" Spruce S07W 6.15' old blazes 1980 NBT 9" W.Birch S80W 14.3' mrkd "MC NBT"

4" Balsam N60E 3.25'

8" W.Birch S80E 17.05'

do

STEPHAN J SZYSZKOSKI

LAND

SURVEYOR

Set sq'd cedar post adjacent.

do

Bearings are magnetic.

Signed by Surveyor's Michigan

33986

Date

11/29/2012

For the Michigan Department of Natural Resources, Forest Resources Division

16963

FORM APPROVED BY MICHIGAN STATE BOA

28, 1971 May 14, 1975

vised Jan., 1983 Rervised Oct., 1995

16965