

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Ontonagon</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 53N R 37W	I5
	T	
	T	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 08/30/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I5) Corner common to Sections 10-11-14-15. July 1967 - Edward W. Charles RLS shows the corner on a
drawing of his survey in Sections 10 and 11 as being monumented with a 1"x3' steel pipe. R.O.W.
marker S35W 66.5', 24" Maple N52W 47.80', Power Pole N60 deg. 30'E, 67', 8" Maple S29E 73.50', I.P.
N0 deg. 37'E, 914.03'. December 1967 - F.J.Bray RLS recovered the same monument and set a 1.25" dia.
iron pipe on the Section line 922.52' west. 1977 - Edward W. Charles again shows the corner on a
drawing for a survey in Section 10.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I5) Found a 1"dia. iron pin in a monument box 6.3' north of the painted C/L of Misery Bay Rd. and
nearly in line with the east edge of Camp 18 Rd. and Superior Rd. The monument is at substantial
record bearing and distance from the remaining three 1967 witnesses: Power Pole NE, 19" Y.Birch NW
(rec. as 24" Maple), and triangular conc. road marker SW. Found the 1967 1.25" I.pipe West 922.28'
(922.52'R) and a 3/4" iron pin northerly 913.69' (914.03'R). Accepted the monument as the best
available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I5) Ed. 1" pin in monument box.
Set measuring nail with MDNR tag in the side of:
Power Pole N66E 67.45'
19" Y.Birch N47W 48.25'
7" Cedar S43E 69.0' mrkd "S14 NBT"
face of triangular concrete marker at ground
S40W 66.3'
Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/29/2012

For the Michigan Department of Natural Resources, Forest Resources Division