

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T 53N R 37W T 53N R 37W T R	MC W. of C5 C7
2. Property Controlling in Section	S T R S T R S T R	
3. Miscellaneous Property in Sec.	S T R S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on MC 08/22/2012
C7 08/28/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC W. of C5) Meander corner on the shore of Lake Superior between Sections 7 and 18. 1980 -
K.L.Sackett RLS established a Witness Corner to the original meander corner, which is shown on the
original plat as being 20.75 chains west of Section corner C5. Set 1"IDx36" I.pipe with 4" alum.
cap. 4" Balsam N69W 5.2', 12" Maple S30E 15.0', 6" W.Birch S45W 11.3'.

(C7) Corner common to Sections 17-18-19-20. 1965 - Remonumented by Billy D. Buckler RLS at the
remains of an old cedar post found at record bearing and distance from original Y.Birch BT N42E 30
links. Set 1"ID I.pipe with 4" aluminum cap. 12" Hemlock N50E 53.5 links, 10" Cedar N50W 81 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC W. of C5) The 1980 monument was recovered in good condition and at record bearing and distance
from two remaining 1980 accessories, described below. The monument was found to be 1308.51' west of
Section Corner C5, making its position 60.99' east of the original M.C. position. Accepted the
monument as a careful and faithful reestablishment of the position of the original corner.

(C7) Found the 1965 monument in good condition and at record bearing and distance from the remaining
1965 witness 18" Hemlock N50E, found in good condition with overgrown blazes. Accepted the monument
as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC) Found 1"ID I.pipe with 4" alum. MDNR cap
for a WITNESS CORNER - the cap is stamped
"Meander cor."
Set measuring nail with MDNR tag in the side of:
13" Maple S28E 15.45' old blazes 1980 BT
8" W.Birch S45W 11.6' scribing plain do
5" Balsam N79W 20.0' mrkd "MC NBT"
8" W.Birch N27E 5.15' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(C7) Found 1"ID I.pipe with 4" alum. MI Dept.
of Conservation cap.
Set measuring nail with MDNR tag in the side of:
18" Hemlock N54E 35.85' old blazes 1965 NBT
9" twin Maple S72E 10.55' mrkd "S20 NBT"
5" Sugar S45W 11.9' "S19 NBT"
6" Sugar N60W 16.8' "S18 NBT"
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/29/2012

For the Michigan Department of Natural Resources, Forest Resources Division

