

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 15 T 53N R 38W	H6
	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16				14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/28/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(H6) Center of Section 15. Not established in the original survey. 1965 - Established by Billy D. Buckler RLS at a position made erroneous due to the remonumentation of Quarter corner G6 in 1982. Mr. Buckler placed two witness corners - south and west of the corner position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H6) Established the corner at the intersection of 1/4 lines. The bearing of the N-S 1/4 line is the mean of the east and west Section lines. The E-W 1/4 line is parallel to the South line of Section 15 between Corners G7 and H7. The position for the corner falls about 3' into the waters of Lake Superior and was not monumented. Established two WITNESS CORNERS as described below. The 1965 witness corners placed by Mr. Buckler were recovered in good condition and were destroyed.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(H6) Witness Corner. Set 1"IDx32" I.pipe with 4" alum. MDNR cap 69.45' west of the corner position and on the E-W 1/4 line. Set measuring nail with MDNR tag in the side of:
5" Spruce N56W 5.8' mrkd "WC BT"
5" Balsam N09W 10.1' do
10" Balsam S60E 19.6' do
6" Maple in clump S45W 22.95' do
Sq'd cedar post adjacent. Bearings magnetic.

(H6) Witness Corner. Set 1"IDx32" I.pipe with 4" alum. MDNR cap 51.12' South of the corner position and on the N-S 1/4 line. Set measuring nail with MDNR tag in the side of:
3" Hemlock S89E 8.4' mrkd "WC BT"
8" W.Birch S18E 8.9' do
9" Cedar N58W 17.6' do
7" Hemlock N23W 18.5' do
Sq'd cedar post adjacent. Bearings magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 08/25/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

