

1998 Presque Isle County State of Michigan Land Corner Remonumentation

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Presque Isle County
(County)

Located In:
Bismarck

Corner Code #

1. Public Land Survey

T 34N R 4E

1-9

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

PRESQUE ISLE COUNTY
RECORDED

98 NOV 25 AM 11:15

Janet M. Lamb
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, James A. Beck, in a field survey on August 6, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1-9

1856 G.L.O. by Alfred Millerd

July 27, 1984 P.A. 74 (Land Corner Recordation Certificate) by

"Set post Cor. of Secs 22, 23, 26 & 27"

Ronald Bischer No. 22428

Hemlock 12 S 68 W 36

Part A: (of Certificate)

Cedar 6 N 55 E 21

GLO Notes

Part B: Fd. 1/2" Rod

Part C: 1/2" Rod

N 12°W 28.95' 9" Lynn

North 33.0' Fe. Cor.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1-9

found 1/2" iron and 15410 (Delmer E. Porter) cap

and the following witnesses:

North 33' Fence corner in poor condition

N 60°E 25.40' 8" Lynn

Ratified by Peer Group
in accordance with P.A. 345

Chairman *Norman J. Dumas*

Date 7/2/98

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-9

1/2" Iron and 15410 (Delmer E. Porter) cap

Witnesses:

North 33' Fence corner in poor condition

N 60°E 25.40' 8" Lynn

N 38 °E 41.34, P.S. 21559 tag in 10" Cedar

S 24°W 50.41', P.S. 21559 tag in 4" Balsam

S 46°W 70.00', P.S. 21559 tag in 8" Balsam

N 30°W 24.50', near face of underground cable marker post

SURVEY &
REMONUMENTATION

JAN 14 1999

SECTION



Signed by *James A. Beck*

Date October 5, 1998

Surveyor's Michigan License No. 21559