

1267

1996 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 319 PAGE 114

For corners in

Presque Isle  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 34N R 5E F-9  
T R  
T R  
T R  
T R  
S T R  
S T R  
S T R  
S T R

2. Property Controlling  
in Section

3. Miscellaneous  
Property in Sec.

PRESQUE ISLE COUNTY  
RECORDED

96 JUL 12 AM 11:39

*Janet M. Lamb*  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, James A. Beck, in a field survey on Apr 22, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

F-9

G.L.O. 1856  
Alfred Millerd

June 26, 1991  
P.A. 132 Survey  
by J. Beck  
Reg. No. 21559

" Set 1/4 Sec. Post  
Beech 10 N85W 11  
Beech 5 S45E 8

1/2" iron and L.S. 21559 cap  
at fence intersection  
Witnesses:  
N 40°W 83.79', nail and cap in 6" Elm  
N15°W 51.34', nail and cap in 6" Elm  
N20°E 21.45', nail and cap in 10" Maple  
N60°E 19.51', nail and cap in 8" Maple

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-9

found 1/2" iron with L.S. 21559 cap  
at fence intersection  
Witnesses:  
N 40°W 83.79', 6" Elm  
N15°W 51.34', 6" Elm  
N20°E 21.45', 10" Maple  
N60°E 19.51', 8" Maple

Ratified by Peer Group  
in accordance with P.A. 345


Chairman *James A. Beck*  
Date 5/22/96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-9

1/2" iron with L.S. 21559 cap  
at fence intersection  
Witnesses:  
N 40°W 83.79', 6" Elm  
N15°W 51.34', 6" Elm  
N20°E 21.45', 10" Maple  
N60°E 19.51', 8" Maple

all witnesses have P.S. 21559 tags



Signed by *James A. Beck*  
Surveyor's Michigan License No. 21559

Date June 17, 1996