

Remonumentation

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

95 JUL 10 AM 9:26

LIBER NO. 2 PAGE NO. 50  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located In:

Corner Code ##

1. Public Land Survey

T10N R 13E

B-5 C-5

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp &amp; File Number

I, John A Milletics, in a field survey on April 10, 19 95,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law, established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

B-5 GLO Notes

Set Post Hemlock 9 N30E 14, Hemloch 24 S14W 29

Act 74 Form Liber 1 Page 159, Act 132 Form Liber 2 Page 515 Liber 3 Page 18

C-5 GLO Notes

Set Post Elm 22 N58°E 20, Birch 20 S59W 31

Act 74 Form Liber 1 Page 155, Act 132 Form Liber 4 Page 204, Unrecorded survey of Section 18  
done for Detroit Edison.Approved Peer Group  
Meeting May 25, 1995

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-5

S 1/4 Cor Section 7 T10N-R13E

Found 5/8" Iron bar as recorded

C-5

SE Cor Section 7 T10N-R12E

Found 3/8" iron bar in pavement

SURVEY &  
REMONUMENTATION

JUL 3 1 1995

COMMISSION



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5

S 1/4 Cor Section 7 T10N-R13E

5/8" iron bar in centerline of gravel road bed

East 94.2 to a nail in a 6" Elm

N80W 29.00 to a nail in a wooden Post

West 33.00 to a 1/2" iron bar

C-5

SE Cor Section 7 T10N-R13E

Monu Box

N45°E 53.2 to a nail in a Fence Post

S45°E 58.6 to a nail in a Fence Post

West 19.2 to the south leg of a Road Sign

S70°E 66.4 to a Road Sign

Signed by

Surveyor's Michigan License No.

25859

Date

May 21, 1995