JAN 2 2 2001

3 mg 54 LIBER

RECEIVED FOR RECORD

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

00 NOV 29 AM 11: 11

Sanilac	Located In:	2000 REMONUMENTATION	PROGRAM
(County)	Localed III,	Corner Code #	
I. Public Land Survey	T <u>lin</u> R TR TR	16E E - 1	
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR		

LIBER NO. 3 -PAGE NO. MICHELE VANNORMAN REGISTER OF DEEDS SANILAC CO. MICHIGAN

Register of Deeds Stamp & File Number

. Lot No	, Recorded Plat
Private Claims	
•	

2000

John A Milletics , in a field survey on May 1 , **19**k do hereby state that under quirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in informance with regulations and rules therefore as required in the current manual of survey instructions of the nited States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or at the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan pard of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, covered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	В	С	D	Ē	F	G	Ħ	1	J	ĸ	L	1
2					T	T	T	T	7	T	T	Ť	_
		1	1-	5-	1	4-	+	-3	†	2	+	i	
3		1	1-	┪	╁╴	1-			+-	 	-	-	_
4	H	Ż	+	8	+-	ģ	٠.	-10	\vdash	11	\bot	1 12—	_
5	H	\vdash	<u> </u>	\vdash	ـــــــــــــــــــــــــــــــــــــ	1		_ _	_	1_			
6	<u> </u>	! [9	<u> </u>	 17	<u> </u>	 6	\perp	-15	L	 14—	L.	 13—	
7		<u> </u>	ļ	_	L.	L	\perp	Ĭ		Ĺ		Ĺ	
8	L.	9	<u> </u> -	0	<u>_</u>	21_	1_	22-	L	3		4	
9			<u> </u>	L_	_	L	L					Ĺ	
10	3	0	-2	او	<u>L</u> ;] 28—	_	27_		 !6		5	
11	_						L	<u> </u>	L	Ĺ		Ľ.	
12	—з	1	3	2—-	_3	 3—.	L] 34—	_3	5	L_3	6—	ĺ
13								1	,	Ĭ		Ĭ	1

Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Hemlock 14" S23°W 19 Links Hemlock 30" S33°E 42 Links Act - 132 - Liber 1 Page 162

Unrecorded surveys - Milletics Oct 1990 State Highway R/W Book page 73

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E - 1NE Corner Section 5 T11N-R16E

Found no evidence or corner at site - State Highway Department removed

corner during construction

West 2693.00 feet to the N 1/4 Corner Section 5 East 2638.57 feet to the N 1/4 Corner Section 4

Accepted as best evidence

APPROVED PEER BOARD MEETING Nov 25, 2000

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NE Corner Section 5 TllN-R16E 1/2" Iron Bar with cap in concrete West 38.03 feet to the SE Corner Section 32 S45°W 69.95 feet to a Right of Way Marker S55°W 55.15 feet to the West leg of a Road Sign N10°W 62.50 feet to a Right of Way Marker N60°W 78.70 feet to a nail in a Light Pole

North 42.45 feet to the W. Leg of a Road Sign West 2693.00 feet to the N 1/4 Corner Section 5

East 2638.57 feet to the N 1/4 Corner Section 4 veyor's Michigan License No.

William to The

Nov 15, 2000 Date