

JAN 22 2001

SECTION

LIBER 3 PAGE 52

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
2000 REMONUMENTATION PROGRAM

RECEIVED FOR RECORD

00 NOV 29 AM 11:11

LIBER NO. 3 PAGE NO. 52
MICHELE VANNORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located in:

Corner Code #

1. Public Land Survey

T11N R16E G - 1

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

2000

John A Milletics, in a field survey on May 1, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, discovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Register of Deeds Stamp & File Number

Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Hemlock 9" S64½W 28 Links

Hemlock 22" S27°E 34 Links

Act 132 - None

L.C.R.C. - Forms - None

State Highway Right of Way Book Page 73

Unrecorded surveys - Milletics Oct 1997 - Milletics May 1998

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G - 1

NE Corner Section 4 T11N-R16E

Found no evidence of corner at site - State Highway Department removed corner during construction

West 2650.92 feet to the N 1/4 Corner Section 4

East 2657.84 feet to the N 1/4 Corner Section 3

Accepted as best evidence

APPROVED PEER BOARD
MEETING Nov 25, 2000

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G - 1

NE Corner Section 4 T11N-R16E

1/2" Iron Bar with cap in concrete

North 3.02 feet to the centerline of M - 46

West 30.36 feet to the SE Corner Section 33

S20°E 42.95 feet to a Stop Sign

N10°E 57.67 feet to a nail in a Power Pole

N45°W 88.10 feet to a nail in a 18" Maple

S15°W 61.95 feet to a nail in a Telephone Pole

West 2650.92 feet to the N 1/4 Corner Section 4

East 2657.84 feet to the N 1/4 Corner Section 3

Witnessed by

John A Milletics

Surveyor's Michigan License No.

25859

Date Nov 15, 2000