

1998

Survey &  
DOCUMENTATION

JAN 22 2001

LIBER

3 PAGE 62

RECEIVED FOR RECORD

00 NOV 29 AM 11:11

LIBER NO. 3 PAGE NO. 62  
MICHELE VANNORMAN  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
2000 REMONUMENTATION PROGRAM

For corners in SECTION

Sanilac Located in: Corner Code #  
(County)

1. Public Land Survey T12N R 16E E - 13  
T R  
T R  
T R  
T R

2. Property Controlling S T R  
in Section S T R

3. Miscellaneous S T R  
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

2000

I, John A Millettics, in a field survey on May 1, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Beech 12" N72°W 27 Links  
Beech 12" N50°E 9 Links

Act 132 - None

Unrecorded surveys-Sanilac Land Survey June 1980, Millettics Oct-Dec 1993, Aug 1995 March 1999  
L.C.R.C. Forms None

Old Survey Liber - None

APPROVED PEER BOARD  
MEETING Nov 25, 2000

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E - 13

SE Corner Section 32 T12N-R16E

Found no evidence of corner on site - Removed by State Highway Department during construction.

West 2652.15 feet to the S 1/4 Corner Section 32

East 2652.60 feet to the S 1/4 Corner Section 33

Accepted as best evidence

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E - 13

SE Corner Section 32 T12N-R16E

1/2" Iron Bar with cap in concrete

East 38.03 feet to the NE Corner Section 5

N40°W 52.48 feet to a nail in a Light Pole

South 57.52 feet to a Right of Way Marker

N40°E 66.96 feet to a Right of Way Marker

N50°E 57.23 feet to W. Leg of a Road Sign

South 38.82 feet to W. Leg of a Road Sign

East 2652.60 feet to the S 1/4 Cor Sec. 33

West 2652.15 feet to the S 1/4 Cor Sec. 33

Signed by John A Millettics

Date Nov 15, 2000

Surveyor's Michigan License No. 25859