

JAN 22 2001

LIBER 3 PAGE 69

RECEIVED FOR RECORD

00 DEC -1 AM 9:33

SECTION

2000 REMONUMENTATION PROGRAM  
 LAND CORNER RECORDATION CERTIFICATE  
 Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 3 PAGE NO. 69  
 MICHELE VANORMAN  
 REGISTER OF DEEDS  
 SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located in:

Corner Code #

1. Public Land Survey

T12N R16E J - 13

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp &amp; File Number

4. Lot No. , Recorded Plat

5. Private Claims

2000

I, John A Millettics, in a field survey on May 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

J - 13

S 1/4 Corner Section 35 T12N-R16E

L.C.R.C. Forms

Act 132 - None

GLO Notes

Beech 7" N40°W 29 Links

Beech 8" N67°E 35 Links

10.85 chains to waters edge

Plat recorded Liber 1 Page 17 Oldfield Add to  
 Taylors Add.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J - 7

S 1/4 Corner Section 35 T11N-R16E

Found no evidence of corner on site - State Highway Department removed  
 corner during construction

West 2640.00 feet the the SW Corner Section 35

Accepted as best evidence

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J - 7

S 1/4 Corner Section 35 T11N-R16E

1/2" Iron bar with cap in concrete

East 49.13 feet to the N 1/4 Corner Section 2

N45°W 60.00 feet to the face of a Light Pole

N30°E 47.35 feet to the face of a Light Pole

N50°E 52.20 feet to the SW Corner of a Building

S45°E 48.95 feet to the NW Corner of a Building

S45°W 53.30 feet to the face of a Light Pole

West 2640.00 feet to the SW Corner Section 35

APPROVED PEER BOARD  
 MEETING NOV 25 2000

Signed by

*John A Millettics*

Date

Nov 15, 2000

Surveyor's Michigan License No.

25859