

SURVEY &
REMONUMENTATION

LIBER 2 PAGE 110

MAR 21 1997

REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

96 DEC 10 AM 11:56

LIBER NO. 2 PAGE NO. 110
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO. MICHIGAN

For corners in COMMISSION

SANILAC
(County)

Located In:

Corner Code ##

1. Public Land Survey T13N R 14E B-13, C-13
T R
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

I, JOHN A MILLETICS, in a field survey on May 25, 19 96,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B - 13 GLO Notes NO Survey in Old Liber
40.00 Set 1/4 Post Unrecorded survey Dates Oct, 1982
Hemlock 10 N 57 E 33 Act 74 None, Act 132 None
Hemlock 12 N 50 W 15 No Road or Drain Comm Records

C - 13 GLO Notes NO Survey in Old Liber
80.00 Set Post Cor Un recorded survey Dated Oct, 1982
Beech 10 N83 1/2 E 12 Act 74 None, Act 132 None
Beech 12 N88 1/2 W 33 No Road or Drain Comm Records

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B - 13
S 1/4 Cor Section 31 T13N-R14E
Found 1/2" Iron Bar set at a
proportion between the SE and SW Corners

C - 13
SE Cor Section 31 T13N-R14E
Found 1/2 Iron Bar set GLO distance
from 1" iron bar to west.

APPROVED PEER BOARD MEETING

12-02-96 JM

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-13
S 1/4 Cor Section 31 T13N-R14E
1/2" iron Bar in gravel road bed
North 33.00 feet to a 1/2" Iron Bar
N05°W 33.40 to a nail in a Power Pole
S70°W 70.40 to a nail in a 10" Ash
West 13.53 to a 1/2" Iron Bar N1/4 Cor of 6
West 2465.13 to SW Cor Section 31

C-13
SE Cor Section 31 T13N-R14E
1/2" Iron Bar in gravel Road Bed
N45°E 59.05 to a nail in a Power Pole
S50°W 65.04 to a nail in a 36" Maple
S30°W 85.33 to a nail in a 18" Maple
West 27.06 to a 1" Iron Bar NE of Sec. 6
West 2665.00 to S 1/4 Cor Section 31

Signed by John A. Milletics
Surveyor's Michigan License No. 25859

Date Aug 3, 1996

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 13, 1975
REVISED MAR. 1983

