

MAY 07 1997

2 PAGE 101

REMONUMENTATION

RECEIVED FOR RECORD

96 DEC 10 AM 11:56

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 2 PAGE NO. 101
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO. MICHIGAN

For corners in

Sanilac

(County)

Located In:

Corner Code #

1. Public Land Survey

T 13N R 16E

B-13

C-13

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

I, John A. Millettics, in a field survey on June 29, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-13 GLO Notes

40.00 Set 1/4 Section Post
Birch 16 N54W 32
Cedar 20 N72E 16

No old Survey Liber
No Act 132 showing corner No Act 74
Information taken from I.E. Choep records

C-13 GLO Notes

80.00 Set Post Corner
Sugar 14 N45E 32
Beech 11 N72½W 38

No Old Survey Liber
No Act 132, No Act 74
Collins Eng. Records

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-13

S 1/4 Corner Section 31 T13N-R16E
Found 1/2" Iron Bar in Gravel Road Bed
Set by I.E.C. on Sectional Breckdown

C-13

SE Corner Section 31 T13N-R16E
Found 5/8" Iron Bar in Gravel Road Bed

APPROVED PEER BOARD MEETING

12-02-96 JM

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-13 S 1/4 Corner Section 31 T13N-R16E

1/2" Iron Bar in gravel Road Bed
N20°W 32.40 to a nail in a 12" Maple
N20°E 31.80 to a nail in a 18" Apple
S45°W 47.85 to a nail in a Fence Post
West 2646.68 to SW Cor of Section
East 2652.94 to SE Cor of Section

C-13 SE Corner Section 31 T13N-R16E

5/8" Iron Bar in gravel Road Bed
East 73.00 to a 1/2" Iron Bar
N50°E 66.90 to a nail in a Power Pole
S45°E 43.65 to a nail in a Power Pole
S50°W 70.10 to a nail in a 36" Ash
West 2652.94 to the S 1/4 Cor
East 2653.88 to the S 1/4 Cor

Signed by

John A. Millettics

Date

Nov 15, 1996

Surveyor's Michigan License No.

25859

