

JAN 21 1999

# SCHOOLCRAFT COUNTY PEER GROUP APPROVED

SECTION

DATE 10/21/98 JOB LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Schoolcraft Located In: Corner Code #  
(County)

1. Public Land Survey T41N R16W B-7  
T R  
T R  
T R
2. Property Controlling S T R  
in Section S T R
3. Miscellaneous S T R  
Property in Sec. S T R

SIGRID HEDBERG  
SCHOOLCRAFT CO. REGISTER 1P  
Page 1 of 1  
JLO Rec. Date 12/03/98 LC 4/ 220  
REVENUE FEES: Time 14:30  
9.00

Register of Deeds Stamp & File Number

4. Lot No. . Recorded Plat
5. Private Claims

I, Thomas P. O'Brien in a field survey on Oct. 23, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7		X											
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

B7 N  $\frac{1}{4}$  Corner Section 19, T41N - R16W  
Sept. 15, 1845 - John Burt D.S. set qr. section post referenced by:  
Y. Birch 8 N35W 4 Hemlock 22 S65E 7

Sept. 25, 1989 - Neil E Hill L.S. recorded an L.C.R.C. (L.2, Pg. 234 L.S. 27447) he indicates "Found 3/4" Pin in Monument Box".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B7 Oct. 23, 1998 - Thomas P. O'Brien P.S. recovered a 3/4" iron pin in Monument Box 8.30' North of M-149 centerline. NBT's recovered varify corner location as found by Hill Sept. 25, 1989.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B7 3/4" Pin in Monument Box, Repainted the blazes on NBT's and made measurements to the following references:

- (Fd.) 10" R.Pine - N33°W - 62.65'
- (Fd.) 6" J.Pine - N48°E - 51.93'
- (Fd.) 8" R.Pine - S 5°E - 43.80'
- (Fd.) 9" S.Pine - S45°E - 74.37'
- M-149 centerline - South - 8.30'
- Carsonite post - North - 30.0'

*Thomas P. O'Brien*

Signed by Thomas P. O'Brien

Date November 29, 1998

Surveyor's Michigan License No. 21274

