

SCHOOLCRAFT COUNTY
PEER GROUP APPROVED

SURVEY &
REMONUMENTATION

DATE 12/2/98 JPB

JAN 21 1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Schoolcraft
(County)

Located In:

Corner Code #

1. Public Land Survey T41N R16W J 3
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

SIGRID HEDBERG 1P
SCHOOLCRAFT CO. REGISTER
Page 1 of 1 LC 4/ 240
JLO Rec. Date 12/15/98 Time 14:22
REVENUE FEES: 9.00

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Thomas P. O'Brien in a field survey on Dec. 11, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3										X			
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- J3 N $\frac{1}{2}$ Corner Section 11, T41N - R16W
Sept. 10, 1845 - John Burt D.S. set Tamarack 3 qr. section corner,
referenced by: Spruce 4 N 21 W 17

April 11, 1995 - LCRC (L.4 Pg.173) by Gerald W. Carlson indicates
"Found a Davis cap (RLS 16926) in a 1" O.D. iron pipe. 0.33' high and
leaning slightly West. Found a rotted, squared, 1.9' high wooden post
0.12' Southeast of pipe."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- J3 Dec. 11, 1998 - Thomas P. O'Brien P.S. recovered 1" O.D. iron pipe
with Davis cap RLS 16926 and rotted squared post laying down and alongside
pipe. Existing witnesses verify corner location as found by Carlson
4/11/95. Reset iron pipe with Schoolcraft County Monument stamped to
identify.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- J3 Schoolcraft County Monument stamped to identify. Repainted blazes
on NBT's and made measurements to the following references:

11" W. Birch - N15°W - 28.67'
9" W. Birch - N3°W - 60.52'
6" W. Birch - N38°E - 24.75' (Tree is leaning)
5" Cedar - S87°E - 17.84'
Carsonite post - East - 1.0'

Thomas P. O'Brien

Signed by Thomas P. O'Brien

Date December 14, 1998

Surveyor's Michigan License No. 21274

