

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 18 T 42N R 14W	4
	S _____ T _____ R _____	(GCDB 120460)
	S 18 T 42N R 14W	3
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	(GCDB 100460)
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32									
13													

I, Stephan J. Szyszkoski, in a field survey on 02/10/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(4-Sec. 18) Northwest 1/16 corner, Section 18. Not previously monumented.

(3-Sec. 18) North 1/16 corner between Section 18 T42N-R14W and Section 13 T42N-R15W. 1969 -
Established and monumented by Frank J. Bray RLS midway and on line between section corner to north
and 1/4 corner to south. Set 1" iron pipe with 4" alum. cap. 9" Y.Birch N25°W 15 links, 14" Cedar
S10°E 121 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(4-Sec. 18) Established the position for the corner at the intersection of the North and West 1/16
lines. The West 1/16 line was run parallel to the N-S 1/4 line of Sec. 18, from 1/16 corner #8.
The North 1/16 line is a straight line between 1/16 corners #3 and #5.

(3-Sec. 18) Found the 1969 monument in good condition, at record bearing and distance from the 1969
BT Y.Birch N25°W, and substantially at the record position between adjacent government corners. I
accepted the monument as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Cedar S72°E 6.03' mrkd "NW1/16 BT"
9" Cedar S02°W 19.73' do
6" Cedar N84°W 15.82' do
13" Cedar N02°E 16.43' do
E= 8068863.511 N= 139804.038

(3) Found 1"ID I.pipe with 4" alum. MI Dept. of
Conservation cap. Set measuring nail with MDNR
tag in the side of:
12" Y.Birch N23°W 9.98' mrkd "1/16" (1969 BT)
7" Balsam S67°E 5.49' "N1/16 BT"
10" Maple S78°W 21.31' do
8" Cedar S32°E 28.14' do
E= 8068428.129 N= 139800.932

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID DL6164: N= 131822.939 m. E= 8059239.498 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 04/07/2015

For the Michigan Department of Natural Resources, Forest Resources Division