

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 4 T 42N R 15W	5
	S 4 T 42N R 15W	4
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 05/06/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 4) North 1/16 corner, Section 4. Previously monumented by Thomas O'Brien PS 21274.

(4-Sec. 4) Northwest 1/16 corner, Section 4. Previously monumented by Thomas O'Brien PS 21274.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 4) The position for this corner, using the dimensions given on the original plat of this
township, is on a straight line between the Center of Section 4 20.00 chains south and 1/4 corner F1
20.69 chains north. Found a 1/2" rebar with plastic cap "O'Brien 21274" substantially at this
position and accepted same as a careful and faithful establishment of the position of the corner.

(4-Sec. 4) The position for this corner is at the intersection of straight lines connecting opposite
1/16 corners. Found a 1/2" rebar with plastic cap "O'Brien 21274" substantially at this position
and accepted same as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Found 1/2" rebar with plastic cap PS #21274.
Set measuring nail with MDNR tag in the side of:
7" Sugar S27W 11.5' mrkd "N1/16 BT"
9" Maple N56W 20.8' do
12" Sugar N35E 27.55' do
Found 1.75" OD iron pipe N70E 10.25'
4" wood post adjacent.
E= 8062785.357 N= 142993.323

(4) Found 1/2" rebar with plastic cap PS #21274
Set measuring nail with MDNR tag in the side of:
12" Maple N77E 46.8' mrkd "NW1/16 BT"
14" Maple N15E 24.65' do
15" Cherry S71W 23.3' do
10" Maple S49E 7.2' do
4" wood post adjacent.
E= 8062380.982 N= 142992.000

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID DL6164: N= 131822.939 m. E= 8059239.498 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/05/2013

For the Michigan Department of Natural Resources, Forest Resources Division

