

JAN 21 1998

SCHOOLCRAFT COUNTY
PEER GROUP APPROVED

DATE 10/15/97

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Schoolcraft
(County)

Located In:

Corner Code #

- | | | | |
|------------------------------------|------|----------|-------|
| 1. Public Land Survey | | T42NR16W | L-9 |
| | | T___R___ | _____ |
| | | T___R___ | _____ |
| | | T___R___ | _____ |
| 2. Property Controlling in Section | S___ | T___R___ | _____ |
| | S___ | T___R___ | _____ |
| 3. Miscellaneous | S___ | T___R___ | _____ |
| Property in Sec. | S___ | T___R___ | _____ |

Received & Filed this 9 day of
December 1997 at 3:54 PM

Sigrid I. Hedberg
Schoolcraft Co. Reg. of Deeds

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Thomas P. O'Brien, in a field survey on Nov. 7, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

- L-9 N 1/4 Corner Section 25
Aug. 8, 1850 - Algernon Merryweather D.S. set qr. section post.
Spruce 6 N43E 10 lks. Cedar 12 South 9 lks.

Oct. 8, 1987 - Gerald L. Wiggins L.S. " Corner set midpoint on line between S.W. Section Corner and S.E. Section Corner of Section 24.
Distance to stream East fits original call." LCRC recorded Liber2, page 114.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- L-9 Nov. 7, 1997 - Thomas P. O'Brien P.S. recovered a 1" iron pipe with 4" aluminum cap as set by Gerald L. Wiggins L.S. on Oct. 8, 1987.
Witnesses found verify corner location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- L-9 1" iron pipe with 4" aluminum DNR cap stamped to identify.

Witnesses: (Fd.) 6" Dead Tamarack - N33°W - 42.3'
(Fd.) 4" Sq. Post - S45°W - 1.0'
NBT. 8" Cedar - S84°E - 161.39'
NBT. 4" Willow - S67°E - 14.57'
NBT. 4" Willow - S14°W - 12.62'
C/L R/R Grade- East - 122.0'



Signed by Thomas P. O'Brien P.S.

Date November 26, 1997

Surveyor's Michigan License No. 21274