

# LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Schoolcraft

Located In:

Corner Code ##

1. Public Land Survey

T 44N R 13W

F9

T R

T R

T R

2. Property Controlling  
in Section

S 20 T 44N R 13W

7

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

7 February 02, 1993

I, Stephan J. Szyszkoski, in a field survey on F9 June 03, 1993, 19\_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

(F9) Quarter corner common to Sections 21-28. Corner previously recorded by David B. Babbitt, RLS in 1983 as a 1" pipe with the following NBTs: 14" Y. Birch S54E 74.4', 14" H. Maple S32W 43.95', 24" H. Maple N89W 37.5'. Corner lies in c/l of e-w road in line with old fence north.

(7) North 1/16 corner between Sections 20-21. Corner not established in the original survey. Found no subsequent record.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F9) Found Babbitt's pipe as recorded but with top bent over by grader. Replaced the pipe with a new 1"x32" iron pipe and plastic cap stamped "Mich DNR LS 33986" 6 in. below gravel surface at the location of the base of the 1983 monument and in accord with the 1983 witnesses. Placed measuring nails with tags in the record witness trees and remeasured as described below.

(7) Found no evidence of previous monumentation or evidence of use. Established corner midway and on a straight line between Section corner 1320.79' north and quarter corner 1320.79' south. At the position for the corner, I placed a 1"x32" painted iron pipe capped with a 4" dia. cast aluminum MONR tablet.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F9) Set 1" iron pipe with plastic cap.  
14" Y. Birch S54E 75.05' nail and tag  
14" H. Maple S32W 44.3' nail and tag  
24" H. Maple N89W 38.0' nail and tag.  
Cor. fence post (fence N-E) N10E 40.65'  
(this is a newer fence, not the fence noted in the 1983 record).  
Bearings are magnetic.



(7) Set 1" pipe with 4" aluminum cap.  
Blazed, scribed, and set measuring nails in the following bearing trees:  
6" Cedar S81W 7.0' "1/16S BT"  
8" Cedar S40W 16.3' "1/16S BT"  
10" Cedar S55E 8.3' "1/16S BT"  
5" Cedar N20W 4.2' "1/16S BT"  
Placed a squared cedar post adjacent to the corner. Bearings magnetic.

Signed by

Stephan J. Szyszkoski

Date

6-24-93

Surveyor's Michigan License No.

33986