

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 31 T 44N R 13W	B12
	S 32 T 44N R 13W	12
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 01/24/2012 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B12) Center of Section 31. Not previously monumented.

(12-Sec. 32) South 1/16 corner, Section 32. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B12) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners 2564.81' west, 2651.75' north, 2646.95' east, and 2617.41' south.

(12-Sec. 32) Computed the position for the corner midway and on a straight line between Quarter corner 1316.98' south and the intersection of 1/4 lines of Section 32 1316.98' north. I found a plastic-capped iron, set flush, stamped "Wiles 43075" N03E 0.26' from said computed position and I accepted the iron as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B12) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
8" Tamarack N41E 24.5' mrkd "CS BT"
7" Tamarack S77E 15.7' do
7" Tamarack N08E 25.25' do
11" Cedar S63W 13.7' do
Bearings are magnetic.

(12) Found iron with cap "Wiles 43075", flush. Set measuring nail with MDNR tag in the side of:
10" Sugar N49W 35.1' mrkd "S1/16 BT"
10" Sugar N07W 23.5' do
7" Sugar N43E 27.55' do
5" Cherry S53W 42.45' do
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/08/2012

For the Michigan Department of Natural Resources, Forest Resources Division

