

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Schoolcraft

(County)

Located in:

Corner Code #

1. Public Land Survey

T R
T R
T R
T R

2. Property Controlling
in Section

S 32 T 44N R 13W 11
S 32 T 44N R 13W 8

3. Miscellaneous
Property in Sec.

S T R
S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Jan 29 2002

I, Stephan J. Szyszkoski, in a field survey on , 20 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:
(11-Sec. 32) Southwest 1/16 corner. Not established in the original survey.
(8-Sec. 32) West 1/16 corner, Section 32. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 32) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.
(8-Sec. 32) Established the corner midway and on a straight line between Quarter corner 1318.24' west and Center of Section (unmonumented intersection of 1/4 lines) 1318.24' east. The corner falls south of a NW-SE trail road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx36" I.pipe with 4" alum.

MDNR cap. Blazed, scribed, and set

measuring nails in:

8" Cedar N83E 24.5' "SW1/16 BT"

5" Tamarack S51E 19.75' do

5" Tamarack S03E 30.35' do

14" Cedar N74W 24.4' do

Bearings are magnetic. Distances are to

nail with tag. Placed a cedar post

adjacent.

(8) Set 1"IDx36" I.pipe with 4" alum.

MDNR cap. Blazed, scribed, and set

measuring nails in:

8" Maple N58E 27.6' "W1/16 BT"

5" Maple S38E 17.85' do

5" Maple S43W 3.4' do

6" Maple N60W 29.7' do

Set cedar post adjacent. Bearings are

magnetic. Distances to nail with tag.



Signed by

Stephan J. Szyszkoski

Date

4/16/02

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Office of Property Management

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995