

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 14W	I3
	T R	
	T R	
2. Property Controlling in Section	S 3 T 46N R 14W	11
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on I3 04/28/2010 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I3) Corner common to Sections 2-3-10-11. 1850 - Established by Guy Carleton Deputy Surveyor. Set post. W.Pine 30" S02W 40 links, Cedar 10" N14E 41 links. The orig. random line notes show the corner is 0.50 ch. east of a stream, 75 links, Course South (likely measured to nearest 1/2 ch.). Found no subsequent record.

(11-Sec. 3) Southwest 1/16 corner, Section 3. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I3) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner by double proportionate measurement to the original record using monumented Quarter corners 2654.40' west (40.525 ch. R), 2649.53' north (40.45 ch. R), 2650.21' east (40.46 ch. R), and 2645.06' south (40.38 ch. R). The position for the corner falls on the bank of the Fox River and cannot be adequately monumented. Established a Witness Corner 5.00' east of the corner position and on the Section line I3 - J3. The top of the NE bank of the Fox River is 3 ft. SW of the Witness Corner.

(11-Sec. 3) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I3) Set 1"IDx36" I.pipe with 4" alum. MDNR cap for a Witness Corner 5.00' east of the corner position and on the Sec. line btwn Sec. 2 and 11 Set measuring nail with MDNR tag in the side of:  
14" W.Spruce N04E 17.95' mrkd "S2 NBT"  
8" Cherry N63E 19.05' do  
9" Maple N84E 10.5' do  
6" Balsam S41E 18.2' "S11 NBT"  
Bearings are magnetic.

(11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
7" J.Pine S60E 39.9' mrkd "SW1/16 BT"  
7" J.Pine S25E 48.9' do  
5" W.Pine S55W 5.3' do  
8" J.Pine N38W 36.2' do  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 12/01/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

