

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 3 T 46N R 14W	5
	S 3 T 46N R 14W	8
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 5 04/29/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 3) North 1/16 corner, Section 3. Not established in the original survey.

(8-Sec. 3) West 1/16 corner, Section 3. Established by Eino Sainio RLS 7873, date unknown.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 3) Established the corner on a straight line between Center of Section 1329.69' south and
Quarter corner 1301.70' north. The position is proportionate to the dimensions derived from the
original plat of this township, 20.1425 chains and 19.7175 chains, respectively.

(8-Sec. 3) Found a 1/2" iron pin with plastic cap stamped 'Sainio LS 7873', in good condition.
Verified the position of the monument with respect to Quarter corner 1330.62' west and Center of
Section 1330.24' east and accepted same as a careful and faithful establishment of the position of
the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
16" R.Pine S46W 12.7' mrkd "N1/16 BT"
11" J.Pine S34W 27.1' do
11" twin R.Pine N60E 46.9' do
16" twin R.Pine N60W 53.15' do
Bearings are magnetic.

(8) Found 1/2" iron pin with plastic cap #7873
Set measuring nail with MDNR tag in the side of:
6" Maple S84E 24.1' mrkd "W1/16 BT"
8" W.Birch S07W 29.4' do
6" B.Spruce S80W 7.5' do
10" Maple N44W 18.5' do
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12/01/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

