	LAND CORNER RECO		MIE.	9 36 AH '96 a Smilly "
2. Property Controlling S 1 in Section S 1 3. Miscellaneous S 1	3S. R 13W.  R	K-12	1858 4 PAGE Register of Deeds	Stamp & File Number
<ol> <li>Lot No</li></ol>	ey on June 10  A. 74, Michigan P.A. of 1970, the regulations and rules thereford of States Department of the vand/or that the corner points of the Michigan Board of Profiblished, monumented, re-mone same town and range, mand accessories and/or substantial of the corner of N. 58° 30′ W. 36 Iks. In rod at intersection the of Section 35	are as required in the current Interior, Bureau of Landmentioned in lines 3, 4 and iessional Surveyors or by a sumented, recovered, found by be recorded	Surveys, Inc. (4.79) (5. 18.10) (6. 22.0)	E F G H J K
B. Description of corner evidence found Found 3/4" iron rod per all (4) 1994 wis March 27, 1996 and is accepted as a care	itnesses. Iron was ratifie	d by the Van Buran (	County Pamanum	entation Peer Group ner.
REMONUMENTATION  MAY 1.6 1997  COMMISSION	•		Ratified by Pee accordance with P., Van Buren Count Date 12/18/96	A. 345 of 1990 ly Surveyor
C. Description of monument for corner at Removed found iron and replace County Remonumentation month Accessories:  Nail & Tab in Hickory Cluster Novail & Tab in 16" Cherry N. 25° Nail & Tab in 28" Hickory S. 85° Nail & Tab in 20" Oak N. 88° W.	ed with a standard Van I ument surrounded by sto I. 15° W. 27.58' E. 18.07' E. 22.00' 4.80'	Buren W	ALLEN H. McMACHEN PROFESIONAL	

Signed by\_

Surveyor's Michigan License No.

TE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983