

- copy -

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Washtenaw

(County)

Located In:

Corner Code ~~77~~

- ## 1. Public Land Survey

T 2S R 5E

L-11

T R

T R

T R

T. R.

- ## 2. Property Controlling in Section

S _____ T _____ R _____

S _____ T _____ R _____

- ### 3. Miscellaneous Property in Se

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat

- ## 5. Private Claims

Thomas L. Sutherland in a field survey on October 10, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

[illegible]

- A. Description of original monument and accessories and/or subsequent restoration:

Unknown
G.L.O.

Field Notes

Unknown

- 1) 44" W. Oak S30°W 52 Links
2) 5" Hickory N33°E 21 Links

(SECTION A. CONTINUED ON REVERSE SIDE)

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" Iron Pipe in E-W Fence 1.0 below ground surface surrounded by rocks from remaining witnesses

*Old Witness Found

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set W.C.R.P. Cap on Iron Pipe in E-W Fence 1.0 below ground surface surrounded by rocks.

- *10) In Remnants of E & W Fence Line
*13) South Point of Large Rock NORTH 2.8
*14) 3" Steel Corner Fence Post N30°E 64.21
*15) 3" Steel Corner Fence Post N35°W 66.50
16) 12" Elm S75°W 14.76 to Tag in N.W. Side
17) S.E. Corner Concrete Block Wall N37°W 70.41
18) 16" Elm N88°E 83.43 to Tag in N. side
19) S.E. Corner Tennis Building N38°E 234.22
20) S.W. Corner Tennis Building N04°W 195.84

I conclude that after study of the record documentation and field observations, that this corner is accepted as the best available evidence of the position of the original corner.

Signed by

Thomas L. Sutherland

Surveyor's Michigan License No.

#24620

Date December 11, 1995

*Old Witness Found

- Copy -

(CONTINUED FROM A. ON FRONT)

August, 1951 M.S.H.D.	Grid Book (W.C.R.G.)	Iron Pipe	3) Center of 21" Triple Elm S87°E 112.0 4) 24" Stump N76°W 198.8 5) 18" Stump S76°W 228.4 6) Fence Corner Post S54°E 183' (stadia) 7) 5" Tw. Thornapple S88°E 65.3 (south tree) 8) 9" Walnut S83°W 204' (stadia) 9) 27" Maple S44°W 323' (stadia)
Oct. 10, 1969 Washtenaw Engineering	Survey 2088	Iron Pipe	None
Feb. 9, 1971 Washtenaw Engineering	Survey 2351	Iron Pipe	None
Jan. 26, 1973 Atwell-Hicks H.W. Taft #12032	Survey 505-6	Iron Pipe	*10) In E & W Fence Line 11) 219.40 E. of Iron Pipe in Centerline Seeley Road
Nov. 1, 1975 R.J. Jagow #6998	Survey 505-19		12) 233.87 E. of Iron Pipe on Line Sec. 25 in Seeley Road
Oct. 24, 1977	Survey R-4026	1" Iron Pipe in E-W Fence	*13) South Point of 18" Rock NOR 2.8
Oct. 28, 1977	Act 74 L.C.R.G. Liber 4, Page 352		*14) 3" Fence Post N30°E 64.1
Jan. 19, 1987	Survey R-5565		*15) 3" Fence Post N35°W 66.5
Jan. 20, 1987 Washtenaw Engineering N.N. Fahrner #17620	Survey R-5567		

*Old Witness Found

APPROVED

DATE 11/6/95CO. REP. [Signature]