

MAY 09 1996

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

Washtenaw (County)	Located In:	Corner Code -#
1. Public Land Survey	T 2S R 5E	M-11
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

Copy

REGISTERED
RECORDED
#15411
MICHIGAN
COURT
MAR 29 2 00 PM '96
WASHTENAW COUNTY, MI
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K
2	6		5		4		3		2		
3											
4	7		8		9		10		11		
5											
6	18		17		16		15		14		
7											
8	19		20		21		22		23		
9											
10	30		29		28		27		26		
11											
12	31		32		33		34		35		
13											

Thomas L. Sutherland in a field survey on October 6, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- | | | | |
|------------------------|-------------|-----------|---|
| 1815
G.L.O. | Field Notes | Unknown | 1) 16" Lynn S06°E 19 Links
2) 16" Lynn N08°W 50 Links |
| Unknown
H.H. Atwell | Grid Book | Iron Pipe | 3) 12" B. Walnut S40°W 45.0
4) 6" B. Walnut S85°E 27.0
5) 4" Hickory WEST 32.6
*6) SW Corner Section 30, T2S, NORTH 132.45 |

(SECTION A. CONTINUED ON REVERSE SIDE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" Iron Pipe W/ARR #15411 Cap in Monument Box from remaining witnesses.

*Old Witness Found

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I conclude that after careful study of the record documentation and field observations, that this corner is accepted as the best available evidence of the position of the original corner.

- W.C.R.P. Cap on 1" Iron Pipe in Monument Box
- *6) Iron Pipe in Monument Box A-11, T2S, R6E N02°42'E 133.59
 - *8) 22" Hickory N85°W 62.20 to Tag in N. Side
 - *11) Utility Pole N80°E 33.71 to Tag in S. Side
 - *12) 16" Pine N40°W 84.18 to Tag in E. Side
 - 13) 5" Oak S35°W 74.45 to Tag in N.E. Side
 - 14) 12" Oak S35°E 100.27 to Tag in S.W. Side
 - 15) Iron Pipe W/A.L.N.M. Cap #24618 WEST 33.1
 - 16) SW Corner CB Rim N45°E 25.48
 - 17) SE Corner CB Rim N45°W 25.84
 - 18) Back of Curb EAST 19.98
 - 19) Back of Curb WEST 20.12

Signed by Thomas L. Sutherland Date December 12, 1995
Surveyor's Michigan License No. #24620

*Old Witness Found

- Copy -

(SECTION A. CONTINUED FROM FRONT)

Unknown H.H. Atwell	Grid Book	Iron Pipe	*6) SW Corner Section 30, T2S, R6E NORTH 134.03
Sep. 22, 1950 Atwell-Hicks H.S. Hicks	Certificate of Survey	Unknown	None
August, 1951 M.S.H.D.	Grid Book (W.C.R.C.)	Unknown	3) 17" Walnut S43°W 45.0 4) 14" Walnut S71°E 27.0
Dec. 4, 1968 Atwell-Hicks R.J. Jagow #6998	Survey 305-116/ Affidavit	Unknown	None
Jan. 26, 1973 Atwell-Hicks H.W. Taft #12032 Nov. 1, 1975 R.J. Jagow #6998	Survey 505-6	3/4" Iron Pipe in W'ly Lane of Maple Road as occupied	3) 20" Walnut S45°W 45.0 7) 22" Maple N26°W 46.0 *8) 20" Hickory N85°W 62.3 9) R/W Pipe N85°W 33.0
Oct. 24, 1977 Oct. 28, 1977	Survey R-4026 Act 74, L.G.R.G. Liber 4, Page 352	3/4" Iron Pipe	3) 17" Walnut S43°W 44.33 to Nail 5) 6" Quad. Hickory WEST 31.93 to Nail
Jan. 19, 1987	Survey R-5565		10) West Edge Pavement WEST 4.9 *11) Utility Pole N80°E 33.25 to Tag
Jan. 20, 1987 Washtenaw Engineering N.N. Fahrner #17620	Survey R-5567		
Jan. 18, 1988 Midwestern Consulting A.R. Rentschler #15411	Act 74, L.G.R.C. Liber 7, Page 146	Found 3/4" Iron Pipe, Set 1" Iron in Monument Box	*8) SPK. North Side 20" Hickory WEST 62.22 *11) SPK. South Side P.P. N80°E 33.71 *12) SPK. East Side 14" Pine N40°W 84.20

*Old Witness Found

APPROVED

DATE 11/6/95

CO. REP.