

SURVEY &
REMONUMENTATION

FEB 04 2008

IOSCO COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

IOSCO

(County)

Located In:

Corner Code #



12/28/2007 1:14:50 PM
STATE OF MICHIGAN - IOSCO COUNTY
FILED
BONITA M. COYLE, REGISTER OF DEEDS

1. Public Land Survey

T24N R5E
T__R__
T__R__
T__R__
T__R__

G-3

2. Property Controlling
in Section

S__
S__
S__
S__

3. Miscellaneous
Property in Sec.

S__
S__
S__
S__



LCRC 2007 93

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William J. Rigg, P.S., in a field survey on November 9, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

GLO: Set Post
Y: Pine 18" N55E 28 lks
Y: Pine 20" N73W 20 lks

LCRC'S

1986, LCRC 86-07 Lapham accepted fence corner on plat line, set bar and cap

Surveys:

1985 Norstar Surveys found 1/2" rebar with cap
Marvin Pike unrecorded survey find corner
Marvin Pike unrecorded survey find corner
2001 NE Land Surveys found wood hub, no witnesses
2001 Rigg Land Surveying notes 1/2" rebar

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rod in position as shown on LCRC's and surveys. Accepted 1/2" rod as best available position for corner.


ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-06-07

William E. Wood

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced rod with 5/8" rerod and remon cap.

Found South 29.75' 14" Cedar
Found North 12.40' 10" Cedar
Found West 36.08' 15" Cedar
Found North 93.0' South Bank of Creek
Set S50°E 26.15' 16" Cedar



Signed by *[Signature]*
Surveyor's Michigan License No. #41108

Date November 9, 2007