

# SURVEY & REMONUMENTATION

Montmorency County Remonumentation

FEB 13 2006

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Located in:

Montmorency  
(County)

Vienna  
(Township)

Corner Code #

Instrument 200500020592 Liber Page 13 169

1. Public Land Survey

T 31 N R 1 E

I - 13

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

200500020592  
Filed for Record in  
MONTMORENCY COUNTY, MI  
TERESA WALKER  
06-24-2005 At 02:55:23 pm.  
REMONUMENTA 14.00  
Liber 13 Page 169 - 169

Register of Deeds Stamp & File Number

I, Larry G. Beauregard in a field survey on May 2005, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I- 13: Sec. corner common to Sec. 34 & 35, T 31 N, R 1 E.

1840 Lewis Clason D. S., set post. Wit's. mkd. (1) Cedar 6" N60°W 12 L. (7.92') (2) Tam. 12" N12°E 44 L. (29.04')

June 1986 Carl R. Johnson P. S. #30083, (Surveyor for MDNR) set Std. DNR monument and cedar post along side by S. P. method between found, SW corner Sec. 34 and the South 1/4 corner of Sec. 35, on Twp. & 3<sup>rd</sup>. correction line. No evidence of original or subsequent survey. Prepared 18" x 24" Sec. drawing (see copy in dossier). Filed LCRC Rec. L. 1, P. 409. (Wit's. mkd. (3) 6" Spruce N88°W 8.30' (4) 6" Spruce N69°E 7.30'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I- 13: May, 2005 Fnd. DNR monument in good condition with Cedar post along side & wit. #4.

Monument left in place after approval by peer group.

Accepted and approved as a careful and faithful establishment of the position of the corner by the peer group on 5-20-05.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I - 13: DNR Std. monument 1" pipe with 4" Aluminum cap.

Wit's. mkd. & measured.

Note: This corner is 1646.36' East of (I-1), T30N, R1E, on the Twp. & 3<sup>rd</sup> correction line according to survey by Johnson.

S40°E 26.75' 6" Spruce  
N69°E 7.55' 6" Spruce  
S10°E 11.27' 9" Cedar  
S40°W 10.25' 7" Spruce

Placed 60 d spike & P. S. tag #18654 in trees. (Typ.)

APPROVED BY  
PEER GROUP

MAY 20 - 05

L.G.B.

Signed by Larry G. Beauregard

Date June 24, 2005

Surveyor's Michigan License No. 18654

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 1971  
REVISED MAY 14, 1973  
REVISED JAN. 1983  
REVISED OCT. 1985

