

COPY

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Located in: MARQUETTE (County)

Corner Code #

For corners in  
MARQUETTE  
(County)

1. Public Land Survey

T 42N R 26W

L-4

2. Property Controlling

S 12 T 42N R 26W

4

3. Miscellaneous  
in Section  
Property in Sec.S T R  
S T R  
S T RS T R  
S T R  
S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, GERALD W. CARLSON, in a field survey on FEBRUARY 8th, 19 95, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-4: Center Quarter Corner Section 12, T42N-R26W.

Not part of original survey.

1930: Survey notes from the Marquette County Road Commission indicate that the corner is 2 iron shafts, one on top of the other. The following witnesses were established:

4" Spruce N69E, 19.95'

4" Spruce S40W, 26.8'

4: Northwest Sixteenth Corner Section 12, T42N-R26W.

Not part of original survey.

1930: Survey notes from the Marquette County Road Commission indicate that the corner is two iron shafts, one on top of the other.

4" Poplar S66E, 18.2'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-4: Found a 2" iron with a Cedar post on the Westerly side.

4: Found a 2" solid iron.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


L-4: Found 2" iron. Established the following references by measuring to DH nails in:  
 6" Cedar N46W, 4.74'  
 11" Cedar N21E, 14.40'

4: Found a 2" solid iron. Established the following references by measuring to DH nails in:  
 3" Tamarack N86E, 46.58'  
 3" Spruce S50E, 38.07'

7" Spruce S41W, 48.56'

Power Pole 551 S64E, 80.85'

Signed by Gerald W. Carlson Surveyor's Michigan License No. 24589  
 Date 4-28-98  
 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN. 1983  
 REVISED OCT., 1995



Register of Deeds Stamp &amp; File Number

MARQUETTE COUNTY  
RECEIVED FOR RECORD  
1998 APR 29 PM 3:49

Liber 6 R.C. Pgs. 79-

REGISTER OF DEEDS  
MARQUETTE COUNTY