

JAN 18 2001

Approved by Right County
Land Survey Monumentation
Peer Group Under Act 315 of
P.A. of 1990 On 12-13, 2000Donald W. Kinnunen
Chairman
05-229For corners in **SECTION**

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Alger
(County)

Located In:

Corner Code #

- | | | | | | |
|---|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 47N | R | 22W | H09 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling
in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous
Property in Section | S | | T | R | |
| | S | | T | R | |
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on June 10, 2000
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H09: PLS Alfred Millard, DS, 1852. Corrected between Sections 22 and 27. Set quarter
section post. Hemlock 15", N.48°W., 20 links. Y. Birch 18", S.38°E., 36 links. ***** C.C.I.
Co., Land and Timber reports. S. Lowney, Jr., cruiser, 1943 and 1944. Found iron pipe with
brass cap. Unrecorded report. ***** C.C.I. Co., Land Corner Record. Ray J. Brotherton, RLS,
1955. Found iron pipe with bronze cap. No Government BT's noted. Hemlock 12", N.40°E., 3.5
feet, notched reference tree. Unrecorded report. ***** No other subsequent restoration of
record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H09: Found 2" cast steel monument with 3/4" brass cap stamped to identify, dated November 8,
1910. Also found 2 existing Hemlock BT's bearing Northwest and Northeast from monument
position. Corner monument believed to be set by L.E. Adams, County Surveyor, 1909-1913. No
record was found as part of the research for this corner. No original evidence was found.
Corner monument as found is accepted as the best available evidence of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H09: Existing 2" cast steel monument with 3/4" brass cap. Renewed existing BT's with BT
signs and paint. Established new reference trees with BT signs, blazed, scribed and painted.
Set PK nails for measure with aluminum I.D. washers in the following: Ex. BT, Maple 8",
N.60°W., 5.93 feet (blaze scars); Ex. BT, Hemlock 22", N.44°E., 4.20 feet (blaze scars);
Balsam 7", S.60°E., 17.43 feet (BT); Y. Birch 10", S.39°W., 69.53 feet (4S BT). Survey sign
on 6 foot steel post, S.64°W., 2.1 feet. All bearings are magnetic.

Signed by

Robert L. JamrosDate Dec. 17, 2000

Surveyor's Michigan License No.

25849