STHAEA8

DEC 2 7 1999

For corners in	SECTION
	SECTION

as expressed below:

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Agái County Land Survey Remonumentation
Peer Group Under Act 213 of P.A. of 1990 On <u>L 2-8</u> 19 27
Guell Walson
Chairman

	9		
Alger (County)	Located In:	Corner Code #	05-157
Public Land Survey	T <u>48N</u> R <u>15N</u> T R T R	<u>c2</u>	TIME 1:30 p.m.
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Section</li> </ol>	T R S T R S T R S T R		DEC 1.5. 1999  DONALD W. KINNUNEN REGISTER OF DEEDS Register of Deed & Traff Wiffle Mumber
	Recorded Plat		A B C D E F G H J K L M
	, in a field survey onSept		

on this certificate. A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

5 above were in conformance with the rules of the Michigan Board of Land

Decree of a Court of Law; established, re-established, monumented,

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and

C2: PLS \* George E. Adair, DS, 1851. \* Set quarter section post. \* W.Pine 12', N.51 E., 23 links. \* Y.Pine 10', S.34 W., 27 links. \*\*\*\*\* Michigan Department of Conservation, Forestry Division. \* Billy D. Buckler, RLS, 1960. \* This corner was re-established by single proportionate measure and on line between 2 section corners. \* No evidence of original corner. \* Set 1° iron pipe with 4° brass cap. \* 10 Red Pine, (1/4s NBT) N.46 E., 22 links; \* 11° Red Pine, (1/4s NBT) S.30 W., 50 links. \* 7° W.Pine, (1/4s NBT) S.84 E., 67 links. \* Recorded in Liber 2, Page 161, Alger County Corner Records. \*\*\*\*\* No other subsequent restoration of record.

Surveyors or by a

recovered, found

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C2: Located corner search area by calculated position and standard field survey. Found 1° iron pipe with 4° brass cap. Found the references of the 1960 report in good condition and added an additional reference. Corner position as found is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C2: Existing 1" iron pipe with 4" brass cap. \* Renewed existing reference trees with BT signs and paint. \* Added an additional reference tree with BT signs, blazed, scribed and painted. \* Set PK nails with aluminum I.D. washers for measure in the following: Existing - R.Pine 16', N.53 E., 14.80 feet. \* Existing - W.Pine 14', \$.77 E., 44.45 feet. \* R.Pine 24', \$.32 W., 33.91 feet. \* J.Pine 6", N.35 W., 28.50 feet, "1/4s BT". \* Survey marker sign on 6 foot steel post, N.79 E., 1.3 feet. \* All bearings are magnetic.

Signed by

Surveyor's Michigan Licer se No.

**JAMROS** PROFESSIONAL SURVEYOR

OPESSIONA

ROBERT L.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975

REVISED JAN., 1983