

JAN 18 2001

Approved by Alger County  
Land Survey Remonumentation  
Peer Group Under Act 345 of  
P.A. of 1990 On 12-13-2000

Gerald W. Carlson  
Chairman

05-210

For corners in SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Alger

(County)

Located In:

Corner Code #

1. Public Land Survey	T	48N	R	15W	E08
	T		R		
	T		R		
	T		R		
2. Property Controlling	S		T		
in Section	S		T		
3. Miscellaneous	S		T		
Property in Section	S		T		

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

FILED

TIME 8:50 A.M.

DEC 20 2000

DONALD W. KINNUNEN  
REGISTER OF DEEDS  
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on April 18, 2000

do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E08 PLS Geo. E. Adair, DS, 1851. Set quarter section post. W. Pine 34", East, 12 links. Beech 9", S.60°W., 12 links. \*\*\*\*\* Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap from 1 W. Pine (possible) BT bearing East, 12 links. W. Pine stub 48", (¼S NBT) N.25°E., 115 links. W. Pine stub 42" (¼S NBT) S.66°W., 102 links. Liber 2, Page 148, Alger County corner records. \*\*\*\*\* No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E08: Established corner position at the midpoint and on line between section corners, ½ mile North and South. Monument and all accessories of the 1960 report have been destroyed and lost. Corner position as established is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E08: Set 2½" x 30" Berntsen aluminum monument no. A1NB30 with 31/4" aluminum cap stamped to identify corner position. Established new references with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: W. Pine stump 32", S.44°E., 41.52 feet (BT); W. Pine stub 36", S.64°W., 82.82 feet (NBT); Maple 4", N.50°W., 51.26 feet (BT); W. Pine stump 40", N.17°E., 130.62 feet (BT). Survey marker sign on 6 foot steel post, S.29°E., 1.0 feet. All bearings are magnetic.

Signed by Robert L. Jamros

Date Dec 17, 2000

Surveyor's Michigan License No. 25849

