

JAN 18 2001

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Alger County
Land Survey Memorization
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000
Donald W. Kinnunen
Chairman

05-214

Alger
(County)

Located In:

Corner Code #

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

1. Public Land Survey T 48N R 15W I11
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R
4. Lot No. , Recorded Plat
5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Robert L. Jamros, in a field survey on September 27, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I11: PLS Geo. E. Adair, DS, 1851. Set post corner of Sections 26, 27, 34 and 35. Spruce 12", N.51°E., 06 links. Spruce 9", S.40°W., 33 links. ***** C.C.I. Co. J.R. Radcliffe, RLS. I found old stake point in muck and BT remains while running cutting lines. B.D. Buckler set 1" iron pipe with 4" brass cap using my post, 5-16-56. Unrecorded report of 5-28-65. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1956. Set 1" iron pipe with 4" brass cap at corner position found by Bob Radcliffe of Munising, old stake bottom in muck. Blk. Spruce 10", S.06°E., 63 links. Blk. Spruce 10", S.57°W., 20 links. Liber 2, Page 146, Alger County corner records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I11: Found 1" iron pipe with 4" brass cap and 1 of the NBT's of the 1956 report in good condition. NBT bearing Southwest from corner is decayed stump. Existing monument as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I11: Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT with BT signs and paint. Established new reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, Blk. Spruce 18", S.11°W., 49.15 feet (blaze scars); W. Pine 8", N.65°W., 4.70 feet (BT); Blk. Spruce 4", S.81°E., 6.81 feet (BT); Blk. Spruce 6", N.10°W., 19.45 feet (BT). Survey marker sign on 6 foot steel post, S.44°E., 1.5 feet. All bearings are magnetic.

Signed by *Robert L. Jamros*
Surveyor's Michigan License No. 25849

Date Dec. 17, 2000

