

JAN 18 2001

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-1999

Harold W. Colman
Chairman

05-195

For corners in **SECTION** **LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

<u>Alger</u> (County)	Located In:	Corner Code #
	49N 13N	G12
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on September 22, 2000,
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

G12: PLS Francis Colman, DS, 1851. Set quarter section post. Maple 10", N.50°E., 13 links.
Maple 12", S.22°W., 28 links. ***** C.C.I. Co., Land and Timber Examination Report, David C.
West, 1958. Timber cruise sheet for Section 33, East quarter section corner found was a 2"
post and iron pipe with 16" Hard Maple N.B.T. unrecorded. ***** No other corner restoration
of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G12: Found 1 1/4" iron pipe and Hard Maple 18", blazed and scribed. Scribing "NBT" visible.
No original G.L.O. evidence found at corner position. G.L.O. terrain calls to North and
South check reasonably well with 12 link stream 7.45 chains South of corner position
measuring within 12'. Iron pipe found believed to be iron pipe shown on Timber cruise sheet
of 1958. Monumented iron pipe as found and accepted as the best available evidence of the
position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G12: Set over existing pipe a 2 1/4" x 30" Berntsen aluminum monument no. A1NB30 with 3/4"
aluminum cap stamped to identify corner position. Renewed existing N.B.T. with BT signs and
paint. Established new reference trees with BT signs, blazed, scribed and painted. Set PK
nails for measure with aluminum I.D. washers in the following: Ex. NBT, Maple 18", N.19°E.,
15.23 feet; Balsam 4", S.48°E., 3.36 feet (1/4S BT); Maple 9", S.77°W., 43.79 feet (1/4S BT).
Maple 7", N.53°W., 59.27 feet (1/4S BT). Survey marker sign on 6 foot steel post, East 1.5
feet. All bearings are magnetic.

Signed by Robert L. Jamros
Surveyor's Michigan License No. 25849

Date Dec. 17, 2000

