CNUMENTATION

JAN 1 8 2001

RECTION

LAND CORNER RECORDATION CERTIFICATE

Feer Group Under Act 345 of
P.A. of 1990 On 12-(3 19 2000
Gustoutonson

Approved by Alger County

				-	
	11	10	-	1	
	11.	Mu	X		
_		W C		<u> </u>	•
	(Chairman			

For corners in	Filing Requi	rement of Act 74, Mich. P.A	A. 1970 Chairman
Alger (County)	Located In:	Corner Code #	05-205 FILED
Public Land Survey	T 48N R 15W T 49N R 15W T R T R		DEC 20 2000
Property Controlling in Section Miscellaneous Property in Section	S T R S T R S T R R		DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI Register of Deeds Stamp & File Number
4. Lot No, Re 5. Private Claims	ecorded Plat		2 6 5 4 3 2 1 1 3 K L M
do hereby state that under require lines 1 and 2 above were in commanual of survey instructions	onformance with regulations and of the United States Depart a Court of Law and/or that the with the rules of the Michigan blished, re-established, monume	P.A. of 1970, the corner points ment I rules therefore as required in the ci timent of the Interior, Bureau of corner points mentioned in lines 3, Board of Land Surveyors or recovered,	titioned 6 18 17 16 15 14 13 current 7 16 16 17 16 17 17 17 18 17 18 17 18 18 18 19 18 18 18 18 18 18 18 18 18 18 18 18 18

A. Description of original monument and accessories and/or subsequent restoration:

B01: PLS John Burt, DS, 1841. Set quarter section post. Fir 6", N.72°E., 21 links. Fir 9", N25°W., 58 links. **** Michigan Department of Conservation, Forestry Division. Dean C. DeLaMater, RLS, 1954. Set 1" iron pipe with 4" brass cap at proportionate position between section corners. W. Pine stump 36", N.75°E., 50 links. W. Pine stump 30", S.65°W., 37 links. Liber 2, Page 68, Alger County corner records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" iron pipe with 4" brass cap and 1 reference of the 1954 report in good condition. Other reference in N.E. bearing has been lost. Corner monument position lies 9.2 feet South and 13.4 feet West of proportional position between section corners. Existing corner monument as found is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Existing 1" iron pipe with 4" brass cap as found. Renewed existing reference with BT sign and paint. Established additional reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, W. Pine stump 30", S.75°W., 24.90 feet (NBT); R. Pine 8", S.85°E., 11.18 feet (4S BT); R. Pine 8", South 03°E., 33.63 feet (4S BT); W. Pine 6", N.18°W., 24.63 feet (4S BT). Survey marker sign on 6 foot steel post, S.60°W., 1.0 feet. All bearings are magnetic.

Date Surveyor's Michigan License No.

SURVEYOR No. 25849 POFESSIONAL

ROBERT L. **JAMROS** PROFESSIONAL