

JAN 18 2001

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000

Donald W. Carlson
Chairman

For corners in **SECTION**

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Alger
(County)

Located In:

Corner Code #

- | | | | | | |
|-------------------------|---|-----|---|-----|-------------|
| 1. Public Land Survey | T | 50N | R | 13W | M.C. G12-13 |
| | T | | R | | |
| | T | | R | | <u>#004</u> |
| | T | | R | | |
| 2. Property Controlling | S | | T | R | |
| in Section | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Section | S | | T | R | |

FILED 05-191
TIME 8:50 AM.

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Robert L. Jamros, in a field survey on May 30, 2000
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC G12-13: PLS Francis Colman, DS, 1851. Intersect Lake Superior C East and West Southwest
and set meander post. W. Birch 6", S.60°E., 83 links. Maple 5", S.39°W., 103 links. *****
No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC G12-13: Found burnt remains of W. Pine stump, sap grain quite evident, at 14.48 chains
North of section corner to South. Record of G.L.O. W. Pine 8", is 14.47 chains. At 18.60
chains found burnt stub of W. Pine 10", with double hacks on line face. Stub is 12 feet high
and double hacks believed to be part of the original line marking. Found old blaze lines
running North from section corner to South, fanning on East and West sides of line tree
remains and 10" W. Pine stub with double hacks. Established line using evidence as described
and set witness corner position 1224.6 feet North of section corner to South. Record=2246.6
feet. Erosion has moved bluff inland 872 feet. Set monument for witness corner position and
established reference trees.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC G12-13: Set witness corner to Meander Corner, Berntsen aluminum monument no. A1NB30 with
3/4" aluminum cap stamped to identify corner position, 1022.0 feet South of meander corner.
Established the following reference trees with BT signs, blazed, scribed and painted. Set PK
nails for measure with aluminum I.D. washers in the following: R. Pine 10", N.30°W., 20.15
feet (BT); R. Pine 8", N.50°E., 12.61 feet (BT); R. Pine 14", S.46°E., 27.14 feet (BT); R.
Pine 11", S.73°W., 6.18 feet (BT). Survey marker sign on 6 foot steel post, North 1.5 feet.
All bearings are magnetic.

Signed by

Robert L. Jamros

Date Dec. 17, 2000

Surveyor's Michigan License No.

25849

