

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Alpena
(County)

Located In

Corner Code #

1. Public Land Survey	T	29N	R	8E	F-2
	T	29N	R	8E	F-3
2. Property Controlling in Section	S	T		R	
	S	T		R	
3. Miscellaneous Property in Section	S	T		R	
	S	T		R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on July 12, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

F-2 – Center of Section 4, T29N,R8E

This corner was not set during the Original GLO Survey

F-3 – South ¼ Corner Section 4, T29N,R08E

1839 – GLO – Lewis Claison – Set qr. sec. post.
Tamarack 15" N35°W 12 Links
Cedar 6" S35°E 13 Links
1910 – County survey records Jos. W. McNeil survey for
Mr. Johnson in section 4 set ¼ cor. 4&9 and found rotted
stump of one O.B.T. Tam. 15" N35°W 12 O.B.T.
1973 – L.C.R.C. L. 1,P. 23 D. Marlatt P.S.#18660 set Mon.
32.0' West of fence corner which agrees with distance
on Jos. W. McNeil survey.
North 32.3' 16" Maple
N30°E 36.8' 12" Birch
2003 – Thomas L. Fabis Fd. unrecorded Certificate Of Survey
existing concrete monument @ fence corner.
5" Ash N30°W 28.54'
5" Ash N20°E 18.40'
14" Cedar S10°E 63.41'
8" Balsam South 48.42'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

F-2 – Center of Section 4, T29N,R8E

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per
standard BLM procedure (intersection of ¼ lines).

F-3 – South ¼ Corner Section 4, T29N,R08E

Found a concrete monument 2.0' out of the ground
fitting T. Fabis witnesses and survey in section 9.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-2 – Center of Section 4, T29N,R8E

2" dia. aluminum cap on 5/8"x34" rebar

F-3 – South ¼ Corner Section 4, T29N,R08E

Reset conc. mon. flush with ground and added P.S. cap# 33981.

Witnesses:

N72°E 12.10' to set N&T on N side 4" Balsam
S48°E 5.42' to set N&T on NE side 3" Balsam
S20°W 5.30' to set N&T on SE side 7" Twin Maple
N42°W 30.27' to set N&T on NE side 10" R. Maple
Center East – West 2 track road North 90'

Witnesses:

N24°E 20.26' to Fd. N&T on SE side 6" Ash
S07°E 63.60' to set N&T at old N&T on E side 18" Cedar
S12°W 48.50' to Fd. N&T on W side 12" Balsam Fir
N26°W 28.48' to Fd. N&T on E side 6" Ash

Set Blue Carsonite Post w/loc. tag 1' North

Signed by:

Carl T. Kiiskila

Date:

2/9/11

Surveyor's Michigan License No.:

33981

