

1993 ALPENA COUNTY REMONUMENTATION CORNER

008000

LIBR

1 PAGE 286

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
ALPENA COUNTY MI.

DEC 16 10 19 AM '93

Marlene A. Johnston
REGISTER OF DEEDS

For corners in

Alpena
(County)

Located In:

Corner Code ##

- | | | |
|------------------------------------|--------------------------|--------------|
| 1. Public Land Survey | T <u>32N</u> R <u>8E</u> | <u>G - 8</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Duane R. MacNeill, in a field survey on July 30, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1855 - Cedar Post

1887 - County Surveyor Rice found original monument and witnesses.

Witnesses:

Cedar 8 S 41 W 7

Do 14 N 21 E 10

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1981 - 4"x4" Rotting Cedar stake found by Duane MacNeill, 1" pipe set.

Witnesses:

South 3.45' 6" Cedar
N 45° W 5.06' 12" Aspen
S 30° E 8.57' 4" Cedar

All above was found during Remonumentation survey, but 12" Aspen and 4" Cedar were missing.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" pipe replaced by 1/2" rerod bearing appropriately stamped Alpena County Remonumentation Aluminum Cap.

Witnesses:

South 3.42' 6" Cedar Fd.
N 18° W 17.22' 8" Cedar Set
East 18.91' 8" Cedar Set
N 76° W 23.47' 6" Cedar Set

Witnesses were freshened as necessary; nails replaced with duplex nails bearing a brass washer stamped license #19237

Signed by

Duane R. MacNeill

Date December 6, 1993

Surveyor's Michigan License No. 19237

