

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

ANTRIM

(County)

Located In

Corner Code #

1. Public Land Survey	T	29N	R	5W	E-9
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on September 10, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-9 Sec. Corner comm. to sec.'s 20, 21, 28 & 29, T29N, R5W

1839 - GLO - J.H. Mullett - Set post cor. sec.'s 20, 21, 28 & 29.  
Cherry 12" N35°E 27 links  
Pine 30" N78°W 28 links

1957 - MDOC Survey Map - Plan # R-5-H - Kenneth J. Ostling,  
P.S.#10068 - Shows set monument with distances in all four directions.

1957 - Land Corner Record - Kenneth J. Ostling, P.S.#10068 -  
Set DOC mon. by single proportion between section corners one mile North and South. Fd. ½" pipe 58 links North and 88 links West. No supporting evidence and makes east and south lines of sec. 20 far too short. Possibly corner to old unrecorded plot.  
7" Aspen N02°W 21 ½ links  
6" Aspen S63°E 30 links

1998 - MDNR - Survey Map - Plan # R-5-T - Carl T. Kiiskila,  
P.S.#33981  
Fd. DNR mon. Shows corner on map with distances North and East. E8 was set by Kiiskila by single proportion between E7 and E9.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E-9 Sec. Corner comm. to sec.'s 20, 21, 28 & 29, T29N, R5W

DNR Forester, Tim Greco found badly damaged DOC mon. lying on its side. Corner was lying near fd. boat spike. Greco requested corner to be reset. Reset corner by doubling over E7 and E8 per the 1998 DNR survey. Also found ½" pipe N53°W 70.13', same pipe that Ostling referenced in 1957. Found no other evidence to dispute location for the corner. Accepted set DNR mon. as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-9 Sec. Corner comm. to sec.'s 20, 21, 28 & 29, T29N, R5W

Set stamped 4" dia. Alum. cap on 1"x36" galv. pipe

Wit: N35°E 26.59' to set N&T on SE side 14" S.Maple  
S35°E 46.25' to set N&T on SW side 9" R.Maple Clump  
S24°W 52.90' to set N&T on W side 13" R.Maple  
N76°W 50.63' to set N&T on S side 9" Twin S.Maple  
N75°E 6.74' to fd. boat spike  
N53°W 70.13' to fd. ½" pipe  
Corner falls 16' North of E-W C/L 2-track & 31' East of N-S C/L 2-track.  
Set Blue Carsonite Post 1' North



Carl T. Kiiskila

12-17-09

Surveyor's Michigan License No.: 33981