

REMONUMENTATION
APR 06 1995
COMMISSION

Arenac County Remonumentation

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 002 PAGE 034

ARENAC COUNTY
REGISTER OF DEEDS

Dec 29 12 30 PM '94

RECORDED

For corners in

Arenac
(County)

Located In:

Corner Code ##

1. Public Land Survey T 18N R 4E C 9
T _____ R _____
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Register of Deeds Stamp & File Number

I, Craig W. McVean, in a field survey on November 22, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C 9 Set post - J. Burt - 1843
Hemlock 9" N 7-1/2° E 9 L.
Do. 14" S 36° W 23 L.

MDOT witness card - L. 1, P. 204 - found 1/2" pipe 1.5' below road in centerline of N-S road and road W. raised with 1/2" pipe - G. Slattery - 1963.
Recorded Survey - L. 1, P. 354 - found 1/2" pipe - 1978; L. 1, P. 541 - found 1/2" iron - 1986.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C 9 Found 1/2" I.D. (3/4" O.D.) x 18" iron pipe per MDOT witness card and recorded surveys. Removed pipe and found 1/2" I.D. x 24" iron pipe in ring of cobble size stone with wood remains below. Monument accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C 9 Replace 2 iron pipes, stone and wood with 3" Arenac County brass cap on 5/8" x 24" rebar in mon. box.
N 55° E 198.27' to SW. corner concrete foundation House #4989.
N 61° W 165.42' to SE. corner block foundation corner House #5518.
S 60° W 68.08' to nail and tag in NW. side 30" Ash.
S 77° E 125.61' to nail and tag in N. side 30" Maple.

ACCEPTED BY THIS ARENAC COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON
11-17-94
Paul M. Ciosek
PAUL M. CIOSEK P.S., CHAIRMAN



Signed by Craig W. McVean

Date 12/21/94

Surveyor's Michigan License No. 39088