

# Arenac County Remonumentation

LIPER 02 PAGE 59

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Arenac (County) Located In: Corner Code #

1. Public Land Survey	T <u>18N</u> R <u>4E</u>	<u>E 10</u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
2. Property Controlling in Section	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
3. Miscellaneous Property in Section	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
4. Lot No. <u>    </u> , Recorded Plat <u>    </u>		
5. Private Claims <u>    </u>		

RECORDED  
JAN 2 2 12 PM '95  
ARENAC COUNTY  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Craig W. McVean, in a field survey of May 24, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E 10 - Set 1/4 Section Post - J. Burt - 1843.  
B. Ash 9" S 55° W 25 Lks.  
Do, 10" N 17° E 22 Lks.

MDOT Witness Card - L. 1, P. 210 - found 3/8" rebar 5" below road surface. 3' W centerline N and S road - dist. and angle to E 9 and E 11 - G. Slattery - 1963.  
L.C.R.C. - L. 1, P. 49 - 5/8" Iron - McGinnis - 1973.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E 10 - Found 5/8" iron rod - down 0.3' per L.C.R.C. and in agreement with MDOT Witness Card location. Remove 5/8" x 3' long iron rod and excavate down 1' and find 3" dia. wood post 0.3' E. Accept wood post as true corner monument. This is consistent with evidence found at G 10, T18N, R4E, where 5/8" rod was found along side found wood posts. Set 3" Arenac brass cap on 5/8" x 24" rebar with 4" plastic tile sleeve with concrete in center of found wood post - down 0.5'. Monument accepted as the best available evidence of the position of the original corner.

ACCEPTED BY THIS ARENAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 22 NOV 1995  
Paul M. Ciosek  
PAUL M. CIOSEK P.S., CHAIRMAN

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E 10 - 3" Arenac County brass cap on 5/8" x 24" rebar with 4" plastic tile sleeve with concrete.  
N 54° E (N 50° E - MDOT) 60.92' (61.20' - MDOT) to MDOT tag in SE side U.P.  
N 15° W 31.27' to capped 3/8" rebar.  
S 70° E 42.54' to capped 3/8" rebar.  
S 17° E 43.48' to capped 3/8" rebar.  
S 40° W 26.28' to nail and tag in W end 5' CMP.



Signed by Craig W. McVean  
Surveyor's Michigan License No. 39068

Date 12/19/95

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1993  
REVISED MAY 14, 1993