

FEB 18 1994

Arenac County Remonumentation

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 02 PAGE 009

For corners in

Arenac

(County)

Located In:

Corner Code =#

1. Public Land Survey T 18N R 4E F-11
- T \_\_\_\_\_ R \_\_\_\_\_
- T \_\_\_\_\_ R \_\_\_\_\_
- T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
- in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
- Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

RECORDED  
DEC 22 2 15 PM '93  
ARENAC COUNTY  
REGISTER OF DEEDS  
Register of Deeds Stamp & File Number

I, Craig W. McVean, in a field survey on September 16, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

F-11 Set post - J. Burt, 1843.  
Hemlock 6" S 13° E 20 Lks.  
Hemlock 11" N 42° W 17 Lks.

County surveyor notes - 1907. Post - distance and angle ties E & W.  
L.C.R.C. - L. 1, P. 49 - McGinnis - 1973.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-11 Found RR spike per L.C.R.C. - L. 1, P. 49.  
Remove - found 3/8" x 18" rebar down 1.7'. Fits County surveyor distance to W and occupation fence to N & Pl of Road. Monument accepted as the best available evidence of the position of the original corner. Accepted by Arenac County Peer Group on 11-17-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11 Replaced RR spike & 3/8" rebar with 3" Arenac County brass cap on 5/8" x 24" rebar in mon. box.  
N 5° E 89.56' to nail & tag in E side 10" Maple.  
N 41° W 130.47' to nail & tag in NE side 24" Oak.  
S 17° W 81.20' to nail & tag in W side 10" Willow.  
S 61° E 170.84' to nail & tag in NE side U.P.



Signed by Craig W. McVean  
Surveyor's Michigan License No. 39088

Date 12/20/93