LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Arenac	Located	In Corner Code #	201600541	DOC#: 201600541 February 29, 2016 10:45 AM	
(County)	· · · · · ·		Darlene Mikkola Register of Deeds Arenac County, Mi	Fee: \$14.00	
Public Land Survey	T R T R		Page of 1 CD		
Property Controlling in Section	S 30 T 20N R	05E 4, 8		PREMICEO, Print 2001 a 1955 a 1950 a 19	
Miscellaneous Property in Section	S		•	The work of the set of	
	sTR		. Register of	Deeds Stamp & File Number	
4. Lot No:	Recorded Plat:		ABCDE	FGHIJKLM	
5. Private Claims:				4 - 3 - 2 - 1	
I. <u>Joshua R. Davidson</u> , in a field survey on <u>January 14</u> , 2015 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			in 4 7 8 as 5 ant 6 18 17 aith 7	9 10 11 12 13 15 14 13 12 13 12 12 13 12 13 12 13 12 13 12 13 12 13 13 12 13 13 13 14 14 -	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			" _	28 27 26 25 33 34 35 36 36	
A. Description of original monument and accessories and/or subsequent restoration:					
<u>4</u> – NW 1/16 corner s	ection 30	<u>8</u>	– CW 1/16 corner sectio	n 30	
None 1983 – Certificate of Survey, L. 1, p. 491, R. Miller PS # 16050.					
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: No. 47319					
<u>4</u> – NW 1/16 corner s	ection 30	8	– CW 1/16 corner sectio	n 30	
Set 2" stamped aluminum cap on 5/8" x 34" rebar per standard BLM procedure. S9°15'E 2.39' to a found ½" rebar & cap #16050, and S55°00'W 1.93' to a found ½" rebar & cap #50427 not utilized in this survey.		Set 2" stamped aluminum cap on 5/8" x 34" rebar per standard BLM procedure. S30°01'E 3.40' to a found ½" rebar & cap #16050, and S56°46'W 4.08' to a found ½" rebar & cap #50427 not utilized in this survey.			
C. Description of monum	ent for corner and acces	ssories established to perp	etuate locating the position of	f the corner:	
$\underline{4}$ – 2" stamped aluminum cap on 5/8" x 34" rebar. $\underline{8}$ – 2			– 2" stamped aluminum ca	2" stamped aluminum cap on 5/8" x 34" rebar.	
N40°W 2.52' to set nail & tag in SW side 12" White Pine N65 S03°W 34.97' to set nail & tag in E side 18" Red Maple S26 S55°00'W 1.93' to found ½" rebar & cap #50247 S56 S09°15'E 2.39' to found ½" rebar & cap #16050 S30			"E 24.52' to set nail & tag in SE side 12" Oak "E 32.04' to set nail & tag in S side 12" Oak "E 37.18' to set nail & tag in NE side 7" Oak "46'W 4.08' to found ½" rebar & cap #50427 "01'E 3.40' to found ½" rebar & cap #16050 blue post with location tag 1' east		
Signed by: Surveyor's Michigan I	License No.: 466		Date: February 24, 2016		