

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 47N R 33W	E8
	T 47N R 33W	F5
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on E8 11/03/2009 F5 08/04/2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E8) Quarter corner common to Sections 20 and 21. 1981 - Remonumented by K.L.Sackett RLS at record bearing and distance from stump of probable original B.T. White Pine N71 1/2W 31 links which was mentioned in old Northern Paper Mills notes as being the original BT. Set 1"IDx36" I.pipe with 4" aluminum MDNR cap. 6" Balsam S82W 13.9', 5" Balsam N20E 9.8', 4" Balsam S22E 12.8'.

(F5) Quarter corner common to Sections 9 and 16. 1852 - Established by Deputy Surveyor Francis Houck S89 deg. 54'W 39.955 chains from Section corner 9-10-15-16. Set post. Fir 8 N44W 39 links, Sugar 14 S75E 18 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E8) Found the 1981 monument in good condition and at record bearing and distance from the 1981 NBT Balsam NE and Balsam SW, both in good condition with overgrown blazes. The NBT Balsam SE is dead and down. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(F5) The original post and accessories were not recovered. Found a 1.5" ID iron pipe with Champion International Corp. location poster fixed to an adjacent 12" Sugar. The pipe is S89 deg. 39'28"W 2633.19' (39.897 ch.) from a pipe accepted by the undersigned as marking the position of Section corner G5. I accept the pipe as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E8) Fd. 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 8" Balsam N24E 10.0' old blazes 1981 NBT 9" Balsam S84W 14.0' do do 7" W.Birch N03E 4.7' mrkd "1/4S NBT" 6" Poplar S22E 15.4' do Set sq'd cedar post adjacent. Bearings are magnetic.

(F5) Found 1.5" ID iron pipe Set measuring nail with MDNR tag in the side of: 8" Balsam N68E 6.8' mrkd "1/4S NBT" 12" Sugar S54E 4.6' do 2" Maple S81W 8.1' " X X " 6" Balsam N53W 2.9' "1/4S NBT" Set sq'd cedar post adjacent. Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 04/26/2012

For the Michigan Department of Natural Resources, Forest Resources Division

