LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For comers in

Baraga (County)	_ Located In:	Corner Code #							
1. Public Land Survey	T 47N R 34W T R	К7					:		
2. Property Controlling in Section	S T R R 34W S T R	15							
3. Miscellaneous Property in Sec.	S T R R R		:	Regis	ter of Dee	eds Stamp	& File !	Number	
4. Lot No. , Red 5. Private Claims	corded PlatK7 03/	05/2009	1 2	A B	C D E	FG	H 1 -3	J K	L M
I, Stephan J. Szyszkoski , ir that under requirements of P.A.	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requi	26/2009 do hereb	1 and 2		8	9-	-10-	-11-	12
instructions of the United States I a Court of Law and /or that the c	Department of the Interior, Bureau of Lorenter points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	and Management or by a o d 5 above were in conforma	decree of 6 ance with 7	-	17	-16 -21	-15	-14 -23	-13-
re-established, monumented, recove			10	30-	29	28	-27-	<u> </u>	25
on this certificate.	31-	32	33	_34_	_35	36			

- A. Description of original monument and accessories and/or subsequent restoration:
- (K7) Corner common to Sections 13-14-23-24. 1852 Established by Z.B.Searles Deputy Surveyor. Set post. Y.Birch 16" S50W 25 links, Maple 10" N65E 24 links. March 1958 - Liber 2 of LCRC Page 213, J.P.Smallwood RLS found 3" sq. spruce post. 5" Balsam East 13.00', 14" Maple S40W 4.75', 18" Pine N55W 22.30'. 1979 - K.L.Sackett RLS found post set by J.P.Smallwood and replaced it with a 1"IDx36" I.pipe with 4" alum. cap. 18" W.Pine N52W 21.4', 12" Maple S50W 4.8', 8" Balsam S87E 12.4'. Rec. Liber 1 of LCRC, Page 377.
- (15-Sec. 13) West 1/16 corner between Sections 13 and 24. Not established in the original survey.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K7) Found the 1979 monument in good condition and at record bearing and distance from the NBT Maple SW, in good condition with overgrown blazes. The NBT W.Pine NW and Balsam SE were not found and their remains are obscured from view by deep snow. Accepted the monument as the best available evidence of the position of the original corner.
- (15-Sec. 13) Established the corner midway and on the Section line between Section corner 1328.89' west and Quarter corner 1328.89' east.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (K7) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 14" Maple \$50W 5.3' old blazes 1979 NBT 12" Y.Birch NO9E 15.5' mrkd "S13 NBT" "S24 NBT" 8" twin Sugar S87E 24.4' 5" Sugar S23E 13.7' "S24 NBT" Cear post adjacent. Bearings are magnetic.

(15) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 3" Tamarack N33E 9.0' "1/16S BT" mrkd 5" B.Spruce S64E 13.0' do 6" B.Spruce S53W 11.45' do 5" B.Spruce N15W 2.2' do Set sq'd Cedar post adjacent. Bearings are magnetic.

Signed by	Stephen	I Sandalest				
Surveyor's M	ichigan License No.	U_	1//	0	33986	
		441.4.			4 of Makeural Danasurana	Affir

09/22/2009

SZYSZKOSKI LAND

CAND

SURVEYOR

STEPHAN J

For the Michigan Department of Natural Resources, Office of Land and Facilities

16296

FORM APPROVED BY MICHIGAN STATE BOARD

sed Jan., 1983

16308