

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 33W	MC S. of A7
	T R	
	T R	
2. Property Controlling in Section	S 19 T 48N R 33W	1
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on MC 10/13/2010 1 10/12/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC S. of A7) Meander corner on the north shore of Vermilac Lake on the Range line between Section 19
T48N-R33W and Section 24 T48N-R34W. 1846 - Established by Wm.Burt Deputy Surveyor on the Range line
between Section corners 23.40 chains north and 56.60 chains south. Set Cedar post. B.Ash 9" N16
1/4E 9 links, B.Ash 5" N46 3/4W 24 links.

(1-Sec. 19) West 1/16 corner between Sections 18 and 19. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC) The original post and accessories were not recovered. Found no evidence of the position of the
corner, which falls in the waters of Vermilac Lake. Reestablished the corner position on a straight
line between Section corner A7 1573.81' north and Section corner A9 3806.73' south, being
proportionate to the original record. The Meander Corner position was not monumented. Established a
WITNESS CORNER to the Meander Corner on the Section line 60.00' north of the Meander Corner position
and 1513.81' South of Section corner A7. The water's edge falls approx. 30' south of the Witness
Corner.

(1-Sec. 19) Established the corner on the Section line between Sections 18 and 19 1336.26' west of
the Quarter corner and 998.85' east of the Section corner, being 20 chains, proportionate to the
original GLO record, west of the Quarter corner. The position for the corner falls 4.5' south of the
south edge of the pavement of old Hwy M-28.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC) Set 1"IDx32" ID I.pipe with 4" alum. MDNR cap
for a WITNESS CORNER 60.00' north of the Meander
Corner position and on the Section line.
Set measuring nail with MDNR tag in the side of:
7" Spruce N82W 10.1' mrkd "WC BT"
8" Cedar N12E 13.65' do
6" Cedar N46E 21.9' do
4" Cedar N74E 33.65' do
Sq'd cedar post adjacent. Bearings magnetic.

(1) Set 1"IDx32" I.pipe with 4" alum. MNDR cap.
The monument is buried to 6" below grade.
Set measuring nail with MDNR tag in the side of:
Power Pole 77-1402 N62E 96.1'
7" Sugar S45E 30.85' mrkd "1/16S BT"
5" Hemlock S08E 27.75' do
6" Sugar S40W 27.75' do
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/12/2011

For the Michigan Department of Natural Resources and Environment, Forest Management Division

