LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #			
(County)			1		
1. Public Land Survey	T 48N R 33W	9 G5			
2. Property Controlling in Section	S T R R S 9 T 48N R 33W				
3. Miscellaneous Property in Sec.	S T R S T R				
4. Lot No, Rec	corded Plat		Register	of Deeds	Stamp & File Number
5. Private Claims	G5 10	04/2010	2 - 6	- 5	4
ı, Stephan J. Şzyszkoski , i	× × × × × × × × × × × × × × × × × × ×	30/2010 do hereby state	3		
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2					
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6				-171	6-15-14-13-
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8					

on this certificate.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

re-established, monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

(G5) Corner common to Sections 9-10-15-16. 1852 - Established by Francis Houck Deputy Surveyor. Set Cedar 10" N39W 16 links, Spruce 10" S6E 17 links. 1991 - Plum Creek Timber Co., Inc. records show that a post and location tag were found at the corner.

(4-Sec. 9) Northwest 1/16 corner, Section 9. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G5) The original post and accessories were not recovered. Found 3 old cedar post points, each about 2.5" in diameter, adjacent, rotted off below the water line, marking the corner position. Found a 5" Cedar N43W 9.2' with Celotex Corp. location poster facing and identifying the corner with initials and earliest date April, 1957. Found a 5" Cedar S18W 14.8' with an old upper blaze facing the corner, and an old 7" Cedar S58W 18.7' with a beaver blaze facing the corner. An old blazed line runs north from the corner position and a blue paint line east. Distances to adjacent corners 1/2 mile N, S, and W and to corner 2 miles east all conform acceptably with the original GLO record. Accepted the posts as the best available evidence of the position of the original corner and replaced them with a monument as described below.

(4-Sec. 9) Established the corner at the intersection of straight lines connecting opposite 1/16

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G5) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Made firm with 5 small cedar posts. Set measuring nail with MDNR tag in the side of: 5" Cedar N40W 12.3' mrkd "S9 NBT" 5" Cedar N88E 11.0' "S10 NBT" 5" Cedar S23W 13.4' "S16 NBT" 6" Cedar S62W 18.1' "S16 NBT" Set sq'd Cedar post adjacent. Bearings are magnetic.

(4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 13" Sugar NO2W 33.45' mrkd "1/16S BT" 8" Sugar S46E 6.8' do 12" Sugar S19W 20.2' do 16" Sugar S81W 17.45' do Set sq'd cedar post adjacent. Bearings are magnetic.

Signed by Surveyor's Michigan License No.

01/12/2011

STEPHAN J SZYSZKOSK

LAND

OF MICH

SURVEYOR

For the Michigan Department of Natural Resources and Environment, Forest Management

16580 16578 FORM APPROVED BY MICHIGAN STATE BOARD

CAND SOUTH rised Jan., 1983 Rervised Oct., 1995

14, 1975